



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 04/07/2022

OUR REF: UAPL1535

REPAIR ESTIMATE TO YOUR TOYOTA ALTIS NO: SLH5601Z

TP Budget Direct
veron.

MROS3ZEE106158126

- 1 FRONT R/H FENDER ASSY *Dented*
- 1 FRONT R/H FENDER INNER SHIELD *new*
- 1 FRONT R/H HEADLAMP ASSY *new*
- 1 FRONT BUMPER FACE *Deland*
- 1 FRONT R/H BUMPER SIDE RETAINER *new*
- 1 FRONT BUMPER REINFORCEMENT *new*
- 10 FRONT BUMPER CLIPS *new*
- 1 FRONT R/H BUMPER FOG LAMP *new*
- 1 FRONT R/H BUMPER FOG LAMP BRACKET *new*
- 1 FRONT R/H BUMPER FOG LAMP OUTER COVER *new*

\$	718.50	✓ 630
\$	236.70	x
\$	1,365.00	✓ 781
\$	668.40	✓ 490
\$	67.30	✓ 35
\$	342.20	x
\$	35.00	✓
\$	266.50	✓
\$	68.70	✓
\$	58.60	x
\$	3,826.90	
\$	956.73	
\$	2,870.18	

LESS 25%..... 2237.50
1678.12

LABOUR CHARGES:-

TO SPRAY UNDERCOATING IN REPAIR

\$ 100.00 40

TO DISM/REWIRE DAMAGED PORTION

\$ 100.00 30

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
RENEW PARTS

\$ 900.00 500

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 900.00 400
\$ 4,870.18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

L/s 04/07/22.

04 Days.

total: 2648.12

L/s: 2.1K.