



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22003470/Vcy3e2-1	
			Date: 05/10/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	YN 6675T	<b>Veh. Inspected</b>	SLG 6554A
	<b>Policy No.</b>	DMCVSNW00108972104	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	SNM22D202517/C02/TANKW	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	BILLY TAN	<b>Assign Date</b>	30/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HYUNDAI TUCSON	<b>c.c</b>	1999
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	KMHJ3813MHU298655	<b>Colour</b>	BLACK
	<b>Odometer</b>	151181 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/50 R18	BRIDGESTONE	6 mm
	<b>L/H Front Tyre</b>	225/50 R18	BRIDGESTONE	6 mm
	<b>R/H Rear Tyre</b>	225/50 R18	BRIDGESTONE	6 mm
	<b>L/H Rear Tyre</b>	225/50 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	12/04/2022	<b>Inspection Date</b>	14/04/2022
	<b>Survey held at</b>	KHEK JOO MOTOR WORKSHOP BLK 9004 TAMPINES IND. PARK 1 #01-94 SINGAPORE 528836		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>13 Working Days</b>	