

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

KDY2318018455

M/s AXA insurance Pte. Ltd
9 North Buona Vista Drive
#18-01/06
Tower 1 The Metroplis
Singapore 138588

30/6/2022

TP AXA

Xiao Chen

Estimate cost of repair to vehicle no: GBD9007C

2pcs Headlamp \$789.98x2 *LH cancelled*
Front Bumper *Deland*
2pcs front bumper bracket \$230.01x2 *RH Bent*
Front Grille *cancelled*
Grille LOGO *per*
Front Nos Photo SP *Cancelled*
Labour for knocking, welding, cutting,
Repairing and replacement of parts.
To spray Paint on the damage Portion
To check wiring.

1579.96	789.98	
792.11	684	2261.36
460.02	230.01	1696.02
496.43		
60.94		S.N: 3U
40.00	30	
300.00	200	
400.00	200	430
40.00	30	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L.

L/S 04/07/22

03 Days

Total: 2156.02

L/S: 1.7K