

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22006283/KVY3E2**Date:** 29/09/2022**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326-01

Date of Loss: 19/06/2022

Nature of Claim: OD

Claim No: MFL2022D0003232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF2758L**
 Make & Model: TOYOTA ALPHARD, 2.5 S CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: 2AR2771314
 Reg. Date: 18/05/2022 (Man. Year: 2022) Chassis No: AYH300142493
 Colour: Metallic Black Odometer: 5671 km
 Engine Capacity: 2493 cc
 Market Value/New Car Price: S\$230,000.00
 Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,101.25	3,666.32	434.93	10.60
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,830.00	1,200.00	630.00	34.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,942.25	4,877.32	1,064.93	17.92
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	5,942.25	4,127.32	1,814.93	30.54
+ GST 7.00/7.00% (\$\$)	415.96	288.91	127.05	30.54
Nett Amount (\$\$)	6,358.21	4,416.23	1,941.98	30.54

INSPECTION

Date of Assignment: 01/07/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 01/07/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2022)

Parts: M1-MPV TOYOTA ALPHARD 2.5 S CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNF2758L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,062.00 F (25/0.00)%	*2,062.00 F (25/0.00)%
2	1		*REAR ALPHARD EMBLEM	Necessary	81.00 F (25/0.00)%	*81.00 F (25/0.00)%
3	1		*E-FOUR EMBLEM	Necessary	69.00 F (25/0.00)%	*69.00 F (25/0.00)%
4	1		*HYBRID SYNERGY DRIVE EMBLEM	Necessary	69.00 F (25/0.00)%	*69.00 F (25/0.00)%
5	1		*RH TAILGATE LAMP	Cracked	756.00 F (25/0.00)%	*730.10 F (25/0.00)%
6	1		*REAR WINDSCREEN - GLASS MOULDING	Necessary	179.00 F (25/0.00)%	*179.00 F (25/0.00)%
7	1		*REAR BUMPER	Bent	2,159.00 F (25/0.00)%	*1,605.00 F (25/0.00)%
8	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
9	1		*INNER SEAL	Necessary	30.00 FS	*30.00 FS
					Sub Total (S\$)	5,445.00 4,865.10
					- List Item Discount on L Items 0.00/0.00% (S\$)	1,343.75 1,198.78
					Total Parts (S\$)	4,101.25 3,666.32

F=Franchise part. S=SpcNett. (x/y)%=(PDisc/Depr)%.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ON REAR END PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	700.00	500.00
2	TO PUTTY ,RESPRAY TAILGATE,BUMPER,END PANEL AND AFFECTED AREAS	New	800.00	500.00
3	TRANSFER PART TO NEW TAILGATE	New	200.00	80.00
4	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
5	CHECK LIGHTING AND WIRING	New	30.00	20.00
Gross Labour Cost (\$\$)			1,830.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >