

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22006288/UQY3M4**Date:** 28/07/2022**REFERENCE**

Insured/Claimant:	SOON JENSON	Policy No:	DMPG21009885	
Date of Loss:	30/06/2022	Nature of Claim:	OD	Claim No: CDMPG22001264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB7337D		
Make & Model:	BMW 216I, 1.5 GT LED NAV (A)	Engine No:	40225262B38A15A
Reg. Date:	17/08/2018 (Man. Year: 2018)	Chassis No:	WBA2D920905K81231
Colour:	Grey	Odometer:	119300 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Premio 7 mm	Rear Left Side:	Premio 7 mm
Front Right Side:	Premio 7 mm	Rear Right Side:	Premio 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,721.80	2,675.80	2,046.00	43.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	307.50	270.00	37.50	12.20
Paintwork Labour	330.64	216.41	114.23	34.55
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,359.94	3,162.21	2,197.73	41.00
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	4,859.94	2,662.21	2,197.73	45.22
+ GST 7.00/7.00% (\$\$)	340.20	186.35	153.85	45.22
Nett Amount (\$\$)	5,200.14	2,848.56	2,351.58	45.22

INSPECTION

Date of Assignment:	01/07/2022	Present Location:	Specialists Motor Pte Ltd (HQ)
Date Inspected:	01/07/2022	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
Parts:	143	BMW 216I 1.5 GT LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB7337D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Dented/Warped	1,275.00 F	*1,250.00 F
2	1	NA	*FRONT BUMPER CLIPS (WCP)	Not Necessary	25.00 F	*- F
3	1	NA	*FRONT BUMPER TRIM (WCP)	Repair	900.00 F	*- F
4	1	NA	*FRT NO PLATE BRKT (WCP)	Bent	78.00 F	*78.00 F
5	1	NA	*FRT UPPER AIR GUIDE (WCP)	Not Necessary	290.00 F	*- F
6	1	NA	*L/A-PILLAR MOULDING (WCP)	Serviceable	75.00 F	*- F
7	1	NA	*L/F GRILLE (WCP)	Cracked	85.00 F	*65.00 F
8	1	NA	*R/A-PILLAR MOULDING (WCP)	Serviceable	75.00 F	*- F
9	1	NA	*R/F GRILLE (WCP)	Cracked	85.00 F	*65.00 F
10	1	NA	*WINDSCREEN (FRONT WINDSCREEN) (WCP)	Broken	820.00 F	*500.00 F
11	1	NA	*WINDSCREEN GARNISH (FRONT WINDSCREEN MOULDING INSTEAD OF WINDSCREEN GARNISH)(WCP)	Necessary	50.00 F	*40.00 F
12	1	NA	*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS
13	1	NA	*SOLAR FILM (FRONT SOLAR FILM)	Necessary	280.00 FS	*200.00 FS
14	1	NA	*WINDSCREEN SEALANT (FRONT WINDSCREEN SEALANT)	Necessary	60.00 FS	*40.00 FS
Supplementary #1						
15	1		*RAIN SENSOR TAPE (WCP)	Necessary	40.00 F	*40.00 F
16	1		*WINDSCREEN NOZZLE (WCP)	Damaged	140.00 F	*140.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,328.00	2,458.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	393.80	217.80
Total Parts (\$\$)	4,721.80	2,675.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	180.00	135.00
2	Total Paint Materials	New	150.64	81.41
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	307.50	270.00
Gross Labour Cost (\$\$)			638.14	486.41

Report was unsubmitted during this print-out.

< END OF ESTIMATES >