

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 04 Jul 2022

Preliminary Advice

Vehicle No	: SJB7337D	Accident Date	: 30/06/2022
Make	: BMW 216I	Policy No.	: DMPG21009885
Assignment Date	: 01/07/2022	Excess	: S\$500.00
Date of Inspection	: 01/07/2022	Est. Duration of Repair	: 4
Inspection At	: SPECIALISTS MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26 SINGAPORE 408711		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,161.94
Revised Amount	:S\$	4,512.94
Check Items (Estimated)	:S\$	55.00
Total	:S\$	4,567.94

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 100,000.00
COE / PARF Rebate	:S\$ 46,699.00
Salvage Value	:S\$

Margin for Repair

:S\$ 53,301.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS AVAILABLE.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.