

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22006291/KCY3M4**Date:** 01/03/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29148219AT2
<b>Claimant Vehicle No :</b>	SMQ8873B	<b>Insured Vehicle No :</b>	SMH3373H
Date of Loss:	30/06/2022	Nature of Claim:	TP
		Claim No:	641966

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMQ8873B</b>	Engine No:	A2191409L77X0233
Make & Model:	OPEL INSIGNIA GRANDSPORT, 1.6 (A)	Chassis No:	W0VZM6EF3K1070588
Reg. Date:	09/12/2019 (Man. Year: 2019)	Odometer:	164131 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 ZR17	Rear Tyre Size:	225/55 ZR17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	Grenlander 7 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	Grenlander 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,170.80	568.80	2,602.00	82.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	995.00	1,975.00	66.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,140.80</b>	<b>1,563.80</b>	<b>4,577.00</b>	<b>74.53</b>
<b>+ GST 8.00/8.00% (S\$)</b>	491.26	125.10	366.16	74.53
<b>Nett Amount (S\$)</b>	<b>6,632.06</b>	<b>1,688.90</b>	<b>4,943.16</b>	<b>74.53</b>

INSPECTION

Date of Assignment:	01/07/2022		
Date Inspected:	04/07/2022	Inspected At:	Munich Autocare Pte Ltd (HQ) 60 Jalan Lam Huat, #07-43 Carros Center Singapore 737869
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	143	OPEL INSIGNIA GRANDSPORT 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ8873B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	530.00 F	*530.00 FL
2	1		*FRT FENDER BRACKET LH	Serviceable	80.00 F	*- FL
3	1		*FRONT FENDER INNER SHIELD LH	Serviceable	115.20 F	*- FL
4	1		*FRONT DOOR LH	Repair	1,809.60 F	*- FL
5	1		*FRONT DOOR CHECK LH	Serviceable	35.00 F	*- FL
6	1		*SIDE MIRROR COVER LH	Cut	102.00 F	*102.00 FL
7	1		*16 ALLOY WHEEL REAR LH	Serviceable	450.00 F	*- FL
8	7		*FENDER CLIP	Not Necessary	49.00 FS	*- FS
					Sub Total (\$\$)	3,170.80 632.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 63.20
					Total Parts (\$\$)	3,170.80 568.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEATING, REALIGN BONNET, FRONT FENDER, FRONT DOOR LH, SIDE MIRROR AND ALL NECESSARY ETC	New	1,500.00	350.00
2	TO CHECK WIRING FOR PROPER FUNCTION	New	120.00	15.00
3	TO APPLY ANTI-RUST	New	150.00	30.00
4	TO PUTTY AND SPRAY PAINTING ON BONNET, FRONT FENDER, FRONT DOOR, SIDE MIRROR AND ALL NECESSARY ETC	New	1,200.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,970.00</b>	<b>995.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >