

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 15 Jul 2022

**Preliminary Advice**

|                    |                                                                                 |                         |              |
|--------------------|---------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SMH3373H                                                                      | Accident Date           | : 30/06/2022 |
| TP Vehicle No      | : SMQ8873E                                                                      | Assignment Date         | : 01/07/2022 |
| Make               | : OPEL INSIGNIA GRANDSPORT B15XHT                                               | Est. Duration of Repair | : 4          |
| Date of Inspection | : 04/07/2022                                                                    |                         |              |
| Inspection At      | : MUNICH AUTOCARE PTE LTD (HQ)<br>60 JALAN LAM HUAT, #07-43<br>SINGAPORE 737869 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,140.80 |
| Revised Amount              | :S\$ | 1,563.80 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,563.80 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( X ) Part-by-Part repair  
 ( ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.