

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SLZ155 H
Date: 1.7.22 13:43

Kia : Sorento : 2015- (UM/UMA) : Front Wheel Drive : Rest of World

Front : Left

Actual	Before	Specified Range
-1°12'	-1°13'	-1°00' 0°00'
3°39'	3°38'	3°53' 4°53'
0°12'	0°14'	-0°03' 0°09'
12°23'	12°23'	12°50' 13°50'
12°15'	12°16'	11°50' 13°50'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°17'	-0°17'	-1°00' 0°00'
3°40'	3°40'	3°53' 4°53'
-0°05'	-0°06'	-0°03' 0°09'
12°58'	12°59'	12°50' 13°50'
12°42'	12°42'	11°50' 13°50'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°56'	-0°56'	
-0°02'	-0°02'	
0°30'	0°30'	
0°03'	0°03'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-3°00'	-3°31'	-1°30' -0°30'
-1°03'	-1°08'	0°00' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°16'	-1°17'	-1°30' -0°30'
0°42'	0°43'	0°00' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°43'	-2°13'	
-0°20'	-0°24'	0°00' 0°24'
-0°53'	-0°55'	