

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHD6480S
Case Reference Number	TAX/06/22/2081
Registration Date	29/12/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TOH ZHI WAI RAYMOND
Type of Accident	Side Swipe
Accident Date and Time	29/6/2022 6:40 PM
Accident Reported Date and Time	30/6/2022 10:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115436
Special Instruction to ARC, if any	TP/ LEFT PORTION
Prepared Date and Time	30/6/2022 10:51 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,028.00	\$800.00
Total Spray Cost	\$2,448.00	\$1,260.00
Total Spare Part Cost	\$7,021.37	\$550.39
Total Other Cost	\$1,141.00	\$40.00
TOTAL COST	\$12,638.37	\$2,650.39
Lump Sum Total	\$12,650.00	\$2,650.00 (L/S)
Number of Repair Days	10.0	7.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / AIG
ARC / Surveyor Sign Off Date	01/07/2022 4:49 PM	01/07/2022 4:00 PM
Signature		
Remarks	LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2207-0107	Invoice Number	
Quotation Date	10.07.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$2,028.00	\$800.00
Total Labour	\$2,028.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$60.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,448.00	\$1,260.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$0.00
Total Other Costs	\$1,141.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given

√ dd
√ nec
√ nec
X nn
R
√ nec
X }nn
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 10/07/2022

User ID PohSuan

	68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	
	69802-21010	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$238.30	0.00	\$0.00	Replace	Not Given	X	} nn
	85720-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$926.00	0.00	\$0.00	Replace	Not Given	X	
	87940-47310	MIRROR ASSY,LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Check	X	} nn
	81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Check	X	
	87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair	R	
	53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	R	
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	√	nec
	53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	√	tn
	53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X	
	53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X	} nn
	53867-47030	SEAL, FRONT FENDER TO COWL SIDE LH	0.00	\$15.20	0.00	\$0.00	Replace	Check	X	
	53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X	
	62120-47021	QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given	X	} nn
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	
	52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	R	
	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X	nn
	67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R	
	68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	
	68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X	} nn
	68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	
	85720-47130	DOOR REGULATOR MOTOR REAR LH	0.00	\$768.90	0.00	\$0.00	Replace	Not Given	X	} nn
	69802-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR LH	0.00	\$224.80	0.00	\$0.00	Replace	Not Given	X	
	61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R	
		STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√	nec
		STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√	nec
	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X	
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	} nn
	65638-47021	FENDER LINER R/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X	
	77350-47030	LID ASSY, FUEL	0.00	\$102.00	0.00	\$0.00	Replace	Not Given	X	} nn
		STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	
Total				\$10,844.61		\$687.97				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	687.99	
	-20%	
	550.39	
+	800.00	L/S \$2,650/-
+	1300.00	
	2,650.39	