

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 199607196R GS1 Reg. No. 19-9607196-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	lef:	CS/AGI22006299/Avy3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	16/08/2022	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMW 5276M	Veh. Inspected		SDG 1638U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10016114/JM	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		01/07/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALPHARD	c.c		2493	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	AGH300040473	Colour		SILVER	
	Odometer	104405 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R17	PIRELLI		6 mm	
	L/H Front Tyre	215/60 R17	PIRELLI		6 mm	
	R/H Rear Tyre	215/60 R17	PIRELLI		6 mm	
	L/H Rear Tyre	215/60 R17	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/06/2022	Inspection Date		01/07/2022	
	Survey held at	SM AUTOMOTIVE				
		BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: