

TPALG
Cenlia.

SKL1103L 2008 May.
Toyota Picnic 1998.
JTEGH233000025539.

Rear Number Plate.	} not over	30(SN) +
Rear Number Plate Holder.		30(SN) +
Rear Bumper. Deformed		548.60 ✓
Rear Bumper Clips. per		30(SN) ✓
Rear Bumper Side Holder x 02.	x 1/2	55.1 x 2 = 110.20 ✓
Rear Bumper Reflector x 02	x 1/2 per	82.1 x 2 = 164.20 +
Rear Bumper Tow Cover x 02.	x 1/2 per	31.1 x 2 = 62.20 +
Reverse Sensor Dented		280(SN) 280(SN)
Rear End Panel. Dented		589.40 ✓
Rear End Panel. Top Garnish. Deformed		255.10 ✓
Rear End Panel Top Garnish Clips. per		20(SN) ✓
Rear End Panel Sealant.	x 1/2	60(SN) ✓ 295.20
Taillamp x 02.	RH and L	295.2 x 2 = 590.40.
Tailgate Dented		1267.90. ✓

SKL1103L.		264.10	✓
Tailgate	lock Damaged		
Tailgate	Weatherstripe. At RH	247.60	✓
Tailgate	Reflector x 02 RH cut	$286.2 \times 2 = 572.40$	✓
Tailgate	Inner Trim Board. NP	409.50	+
Tailgate	Inner Trim Board clips. NP	30(SN).	+
Tailgate	Glass Moulding. } Nec	182.10	✓
Tailgate	Glass Sealant. }	60(SN)	✓
Toyota	Logo } Nec	75.40	✓
Toyota	Wording }	60.90	✓
Picnic	Wording }	68.40	✓
Floor Panel	Reps	989.40	+
Floor Panel	Top Board. Deformed	687.60	✓
Floor Panel	Surround Trim. NP	396.90	+
Rear Fender	Inner Trim Board x 02 LH cracked	$750.5 \times 2 = 1501$	750.50
Rear Fender	Inner Trim Board clips. Nec	60(SN)	✓
		5689.20	
		4266.90	
		S.N: 480	

SKL1103L

- Panel Beating
- Spray Painting.
- Wiring.
- To remove reverse sensor
- To spray tuff coat.
- To remove upholstery.
- To remove rear camera.
- To transfer tailgate fittings
- To remove tailgate g/s??

~~1400~~ 1000

~~1400~~ 1000

~~100~~ 30

~~100~~ 50

~~150~~ 80

~~150~~ 80

~~100~~ 50

2490

~~150~~ 80

~~180~~ 120

total: 7236.50

4/s: 58K

06 Days.

5.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: