

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006310/ECE2**Date:** 01/12/2022**REFERENCE**

Insured/Claimant:	CHONG SI MIN, BERICA	Policy No:	2070132145
Date of Loss:	29/06/2022	Nature of Claim:	OD
		Claim No:	6411940486SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV492T		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZD897824
Reg. Date:	14/09/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF37L1116763
Colour:	Red	Odometer:	30326 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$167,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,818.00	8,119.84	34,698.16	81.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,292.00	9,062.00	8,230.00	47.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	60,110.00	17,181.84	42,928.16	71.42
+ GST 7.00/7.00% (S\$)	4,207.70	1,202.73	3,004.97	71.42
Nett Amount (S\$)	64,317.70	18,384.57	45,933.13	71.42

INSPECTION

Date of Assignment:	01/07/2022		
Date Inspected:	01/07/2022	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Crushed	1,073.00 FS	*858.40 FS
2	1	*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	66.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - RH	Not Necessary	124.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
5	1	*FRONT BUMPER SPOILER	Not Necessary	426.00 FS	*- FS
6	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
7	1	*HEADLIGHT MOUNTING - RH	Not Necessary	132.00 FS	*- FS
8	1	*HEADLIGHT - RH	Not Necessary	5,952.00 FS	*- FS
9	1	*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
10	1	*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
11	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
12	1	*FRONT FENDER - RH	Repair	1,445.00 FS	*- FS
13	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
14	1	*FRONT FENDER BRACE - RH	Not Necessary	98.00 FS	*- FS
15	1	*FRONT FENDER BRACKET - RH	Not Necessary	39.00 FS	*- FS
16	1	*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	37.00 FS	*- FS
17	1	*FRONT FENDER INSULATION - RH	Not Necessary	48.00 FS	*- FS
18	1	*FRONT WHEEL HOUSING LINER - RH	Not Necessary	260.00 FS	*- FS
19	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
20	1	*FRONT WHEEL HOUSING LINER COVER - RH	Not Necessary	18.00 FS	*- FS
21	2	*FRONT WHEEL ARCH COVER - LH / RH	Cut	566.00 FS	*452.00 FS
22	1	*FRONT DOOR - RH	Repair	3,017.00 FS	*- FS
23	1	*FRONT DOOR OUTER SEAL - RH	Not Necessary	185.00 FS	*- FS
24	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	164.00 FS	*- FS
25	1	*FRONT DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
26	1	*FRONT DOOR COVER - RH	Cut	283.00 FS	*226.00 FS
27	1	*WING MIRROR MOUNTING - RH	Broken	2,278.00 FS	*1,822.40 FS
28	1	*WING MIRROR CAP - RH	Missing	203.00 FS	*162.40 FS
29	1	*WING MIRROR GLASS - RH	Not Necessary	1,052.00 FS	*- FS
30	1	*FRONT DOOR CORNER TRIM - RH	Cut	51.00 FS	*40.40 FS
31	1	*FRONT DOOR WINDOW GUIDE - RH	Not Necessary	481.00 FS	*- FS
32	1	*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	Cut	287.00 FS	*229.60 FS
33	1	*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	Cut	251.00 FS	*200.80 FS
34	1	*REAR DOOR - RH	Repair	3,127.00 FS	*- FS
35	1	*REAR DOOR OUTER SEAL - RH	Not Necessary	151.00 FS	*- FS
36	1	*REAR DOOR ATTACHMENT PARTS	Not Necessary	324.00 FS	*- FS
37	1	*REAR DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
38	1	*REAR SILL PANEL SEAL - RH	Not Necessary	151.00 FS	*- FS
39	1	*REAR DOOR COVER - RH	Cut	270.00 FS	*216.00 FS
40	1	*REAR WHEEL HOUSING LINER - RH	Not Necessary	262.00 FS	*- FS
41	1	*REAR WHEEL SPOILER - RH	Not Necessary	44.00 FS	*- FS
42	1	*SIDE MEMBER TRIM - RH	Not Necessary	189.00 FS	*- FS
43	1	*REAR DOOR HANDLE EXTERIOR - RH	Repair	222.00 FS	*- FS
44	1	*REAR DOOR HANDLE HOUSING - RH	Not Necessary	31.00 FS	*- FS
45	1	*REAR BUMPER	Repair	1,738.00 FS	*- FS
46	1	*REAR BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
47	1	*REAR BUMPER SPOILER	Cut	510.00 FS	*408.00 FS
48	1	*REAR BUMPER CROSS REINFORCEMENT - CENTER	Not Necessary	108.00 FS	*- FS
49	1	*REAR BUMPER BRACKET - RH	Not Necessary	53.00 FS	*- FS
50	1	*REAR LIGHT REFLECTOR - RH	Not Necessary	46.00 FS	*- FS
51	2	*REAR WHEEL ARCH COVER - LH / RH	Cut	566.00 FS	*452.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*REAR ALUMINIUM RIM Rear O/S Not Necessary	Frnt O/S Cut	2,828.00 FS	*1,131.20 FS
53	1	*RUBBER VALVE (4PCS)	Necessary (1Pc Only)	15.00 FS	*2.96 FS
54	1	*SUSPENSION SUBFRAME ASSEMBLY CARRIER	Not Necessary	751.00 FS	*- FS
55	1	*SUBFRAME BONDED BRUSHES - UPPER / LOWER	Not Necessary	178.00 FS	*- FS
56	1	*SUSPENSION TRACK CONTROL ARM	Not Necessary	511.00 FS	*- FS
57	1	*SUSPENSION WHEEL BEARING HOUSING - RH	Bent	751.00 FS	*600.80 FS
58	1	*SUSPENSION WHEELHUB BEARING	Necessary	549.00 FS	*438.80 FS
59	1	*SUSPENSION GUIDE JOINT - RH	Bent	145.00 FS	*115.60 FS
60	1	*SUSPENSION DRIVE SHAFT - RH	Not Necessary	1,517.00 FS	*- FS
61	1	*COUPLING ROD (NPA)	Not Necessary	0.00 FS	*- FS
62	1	*STABILIZER	Not Necessary	456.00 FS	*- FS
63	1	*GAS SHOCK ABSORBER	Bent	338.00 FS	*270.40 FS
64	1	*STEERING GEAR	Not Necessary	5,538.00 FS	*- FS
65	1	*TRACK ROD	Not Necessary	98.00 FS	*- FS
66	1	*TIE ROD END - RH	Bent	126.00 FS	*100.40 FS
67	1	*RHS FRONT TYRE	Torn	310.00 FS	*310.00 FS
68	1	*SUNDRIES	Necessary	900.00 FS	*81.68 FS
69	1	*REAR BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 42,818.00 8,119.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,000.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS REAR DOOR AND DOOR HANDLE	New	4,500.00	2,460.00
7	TO REMOVE AND TRANSFER REAR PARKING AND REAR LID KICK SENSOR	New	360.00	360.00
8	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
9	TO RESPRAY REAR BUMPER AND RHS REAR BUMPER	New	2,000.00	550.00
10	TO RENEW RHS FRONT TYRE WITH RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	560.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			17,292.00	9,062.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >