

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0546/2022/JT
DATE	:	30-Jun-22
WIP	:	30928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/7/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120


Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MRS CHONG SI MIN, BERICA
ADDRESS	:	10 TAO CHING ROAD #18-19 SINGAPORE 618725
TELEPHONE	:	HP +65 93827057
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070132145
VEHICLE NO	:	SMV 492 T
MODEL CODE	:	AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR	:	14/9/2020
ENGINE NO	:	CZD 897824
CHASSIS NO	:	WAUZZZF37L1116763
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	29-Jun-22
PLACE OF ACCIDENT	:	FOUNTAIN ROUNDABOUT

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 492 T - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	560
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	? /
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00	1099
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS REAR DOOR AND DOOR HANDLE.	\$ 4,500.00	2469
SUB TOTAL LABOUR CHARGES		\$ 12,580.00	

4 X 550 + 804.80 + 190

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 492 T - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AND AND REAR LID KICK SENSOR.	S/N \$ 360.00	/
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$ 2,000.00	550
4	TO RENEW RHS FRONT TYRE WITH RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 560.00	/ 280
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 17,292.00	

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / CR4 ? X nn	1	\$	1,073.00	✓ 858.40
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$	66.00	
3	FRONT BUMPER GRILLE - RH X nn	1	\$	124.00	
4	FRONT BUMPER CLOSING ELEMENT X nn	1	\$	212.00	
5	FRONT BUMPER SPOILER X nn	1	\$	426.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH X nn	1	\$	171.00	
7	HEADLIGHT MOUNTING - RH X nn	1	\$	132.00	
8	HEADLIGHT - RH X nn	1	\$	5,952.00	
9	LIFT CYLINDER - RH X nn	1	\$	231.00	
10	LIFT CYLINDER HOSE X nn	1	\$	92.00	
11	FRONT BUMPER GUIDE SECTION - RH X nn	1	\$	43.00	
12	FRONT FENDER - RH X R	1	\$	1,445.00	
13	FRONT FENDER ATTACHMENT PARTS X nn	1	\$	66.00	
14	FRONT FENDER BRACE - RH X nn	1	\$	98.00	
15	FRONT FENDER BRACKET - RH X nn	1	\$	39.00	
16	FRONT FENDER CLOSING ELEMENT - RH X nn	1	\$	37.00	
17	FRONT FENDER INSULATION - RH X nn	1	\$	48.00	
18	FRONT WHEEL HOUSING LINER - RH ? X nn	1	\$	260.00	
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ X nn	105.00	
20	FRONT WHEEL HOUSING LINER COVER - RH X nn	1	\$	18.00	
SUB TOTAL SPARE PARTS			:	\$ 10,638.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - FRONT

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL ARCH COVER - LH / RH / <i>cn</i>	②	\$ 566.00	✓ 482.00
22	FRONT DOOR - RH <i>x R</i>	1	\$ 3,017.00	
23	FRONT DOOR OUTER SEAL - RH <i>x nn</i>	1	\$ 185.00	
24	FRONT DOOR ATTACHMENT PARTS <i>x nn</i>	1	\$ 164.00	
25	FRONT DOOR CATCH - RH <i>x nn</i>	1	\$ 134.00	
26	FRONT DOOR COVER - RH / <i>cut</i>	1	\$ 283.00	✓ 226.00
27	WING MIRROR MOUNTING - RH / <i>BR</i>	1	\$ 2,278.00	✓ 1822.40
28	WING MIRROR CAP - RH / <i>mt</i>	1	\$ 203.00	✓ 162.40
29	WING MIRROR GLASS - RH <i>x nn</i>	1	\$ 1,052.00	
30	FRONT DOOR CORNER TRIM - RH / <i>cut</i>	1	\$ 51.00	✓ 40.40
31	FRONT DOOR WINDOW GUIDE - RH <i>x nn</i>	1	\$ 481.00	
32	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH / <i>cn</i>	1	\$ 287.00	✓ 229.60
33	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	1	\$ 251.00	✓ 200.80
34	REAR DOOR - RH <i>x R</i>	1	\$ 3,127.00	
35	REAR DOOR OUTER SEAL - RH <i>x nn</i>	1	\$ 151.00	
36	REAR DOOR ATTACHMENT PARTS <i>x nn</i>	1	\$ 324.00	
37	REAR DOOR CATCH - RH <i>x nn</i>	1	\$ 134.00	
38	REAR SILL PANEL SEAL - RH <i>x nn</i>	1	\$ 151.00	
39	REAR DOOR COVER - RH / <i>cut</i>	1	\$ 270.00	✓ 216.00
40	REAR WHEEL HOUSING LINER - RH <i>x nn</i>	1	\$ 262.00	
SUB TOTAL SPARE PARTS		:	\$ 13,371.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REAR WHEEL SPOILER - RH X nn	1	\$	44.00	
42	SIDE MEMBER TRIM - RH X nn	1	\$	189.00	
43	REAR DOOR HANDLE, EXTERIOR - RH X R	1	\$	222.00	
44	REAR DOOR HANDLE HOUSING - RH X nn	1	\$	31.00	
SUB TOTAL SPARE PARTS		:	\$	486.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - REAR

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
1	REAR BUMPER X R	1	S	1,738.00	
2	REAR BUMPER FIXING PARTS X nn	1	S	220.00	
3	REAR BUMPER SPOILER / cn	1	S	510.00	408.00
4	REAR BUMPER CROSS REINFORCEMENT - CENTER X nn	1	S	108.00	
5	REAR BUMPER BRACKET - RH X nn	1	S	53.00	
6	REAR LIGHT REFLECTOR - RH X nn	1	S	46.00	
7	REAR BUMPER GUIDE SECTION - RH ? X nn	1	S	71.00	
8	REAR WHEEL ARCH COVER - LH / RH / cn	2	S	566.00	452.00
9	REAR ALUMINIUM RIM FM RH / cn Re-4-11	21	S	2,828.00	1131.20 / 1131.20
10	RUBBER VALVE - nc	1	S	15.00	2.96 / 2.96
11	SUSPENSION SUBFRAME ASSEMBLY CARRIER ? X nn	1	S	751.00	
12	SUBFRAME BONDED BRUSHES - UPPER / LOWER ? X nn	1	S	178.00	
13	SUSPENSION TRACK CONTROL ARM ? X nn	1	S	511.00	
14	SUSPENSION WHEEL BEARING HOUSING - RH ? / BT	1	S	751.00	600.80
15	SUSPENSION WHEELHUB BEARING ? ncc	1	S	549.00	438.80
16	SUSPENSION GUIDE JOINT - RH ? BT	1	S	145.00	115.60
17	SUSPENSION DRIVE SHAFT - RH X nn	1	S	1,517.00	
18	COUPLING ROD ? X nn	1		TBC	
19	STABILIZER ? X nn	1	S	456.00	
20	GAS SHOCK ABSORBER ? BT	1	S	338.00	270.40
SUB TOTAL SPARE PARTS				<u>\$ 11,351.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	STEERING GEAR 1 X nn	1	\$	5,538.00	
22	TRACK ROD 1 X nn	1	\$	98.00	
23	TIE ROD END - RH 1 BT	1	\$	126.00	100.40
24	RHS FRONT TYRE 1 Tn (7121)	S/N	TBC	310	310
25	SUNDRIES 1 nec		\$	900.00	81.68 / 81.68
TOTAL SPARE PARTS		:	\$	42,508.00	
TOTAL LABOUR CHARGES		:	\$	17,292.00	
GRAND TOTAL		:	\$	59,800.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (CLKK)
11/7/92, 2.77P

00-1412
EXCESS ?
11 45
P/P
4 02 4

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability for loss of goods is allowed
- Any damaged part(s) must be resurveyed and not subject to final approval from Insurance Company

Authorised by Repairer
Signature:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT