



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-349-TG
DATE : 1-Jul-2022
POLICY NO. :
VEHICLE REG. NO. : SMP2811A
VEHICLE MAKE : MINI COOPER 5DR HB

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper	1	\$ 1,080.70	\$ 1,080.70 <i>Rp</i>
2	Rear Bumper Side Retainer LH	1	\$ 176.70	\$ 176.70 <i>X</i>
3	Rear Parking Sensor LH	1	\$ 348.90	\$ 348.90 <i>X</i>
4	Rear Parking Sensor Retainer LH	1	\$ 43.48	\$ 43.48 <i>X</i>
5	Rear Tail Lamp LH	1	\$ 2,478.30	\$ 2,478.30 <i>ant</i>
6	Rear Tailgate Logo (Cooper)	1	\$ 86.80	\$ 86.80 <i>rel</i>
Parts Less 5%				\$ (210.74)
Total Spare Parts				\$ 4,004.14
SPECIAL NETT				
7	Rear Bumper Clips	10	\$ 5.00	\$ 50.00 <i>3 one</i>
Total Special Nett				\$ 50.00
LABOUR				
8	Repair, Refit, Remove and Replace Affected Accident Parts	1	\$ 400.00	\$ 400.00 <i>200</i>
9	Spray Paint (Rear Bumper), Tailgate	1	\$ 400.00	\$ 400.00 <i>✓</i>
10	Remove and Refit Rear Bumper Sensor	1	\$ 100.00	\$ 100.00 <i>30</i>
11	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 <i>X</i>
12	Check and Rectify Electric Wiring	1	\$ 50.00	\$ 50.00 <i>30</i>
Total Labour				\$ 1,050.00
Amount Before Excess				\$ 5,104.14
Add GST @ 7%				357.29
Total Amount Payable				\$ 5,461.43

Estimate prepared by: James Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749/67583537
WP' 4/7/22 @ 1215
c/s Resurvey after repair
Taufik @ LKK Auto
2 days - 3 days