SNC 5253 Y. TP ALG. Hyundin Avante, Xino Ley KMHLNAIETNU238081

RH Door Devled 1883.10. 495.40. + TH Door Lock 3/14 249.40 Nees RH Dos Wentheslipe Im PH POOR Surround Felt. Cut 150(5N) 8V(5N) Peer Peer RH Poor Black Tape. 80(SN). V 1983.10 S.W:160 1594.48

Penel Benting Spry Pocintry Wiring-To Spay talf cont. To transfer door fitting.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

(2100)

fold: 2614.48 4/3/2.11C