



簡福星嘜工廠
KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147
Tel : (65) 6747 9560, 6858 2126, 6858 4361
Fax : (65) 6748 1006, 6281 8428
E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221468-00E
GST Reg. No. M9-0005333-E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001787351	Date of Loss:	30/06/2022
Vehicle Reg. No.:	SKF6234R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG KIA LIM WILLY		
Make/Model:	VOLKSWAGEN JETTA, 1.4 TSI 1622G5 (A)	Vehicle Reg. Date:	26/07/2011
Vehicle Colour:	Green/Purple		
Engine No:	CAV293175	Chassis No:	WVWZZZ16ZBM101174
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	3,470.50
Miscellaneous Items	0.00
Labour	970.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (\$)	5,640.50
- Excess (\$)	600.00
(S\$)	5,040.50
+ GST 7.00% (\$)	352.84
Nett Amount (\$)	5,393.34

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jul 2022)

Parts: 143 VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER LH	0.00	0.00	*230.00 F
2	1		*FRONT FENDER VERTICAL GARNISH LH	0.00	0.00	*85.00 F
3	10		*FRONT FENDER SHIELD CLIP	0.00	0.00	*55.00 F
4	1		*FRONT DOOR LH	0.00	0.00	*850.00 F
5	1		*FRONT DOOR HINGE TOP LH	0.00	0.00	*45.00 F
6	1		*FRONT DOOR HINGE LOWER LH	0.00	0.00	*65.00 F
7	1		*FRONT DOOR CHECKER LH	0.00	0.00	*55.00 F
8	1		*FRONT DOOR TOP MOULDING LH	0.00	0.00	*110.00 F
9	1		*FRONT DOOR OUTER MOULDING LH	0.00	0.00	*65.00 F
10	1		*FRONT DOOR OUTER HANDLE LH	0.00	0.00	*100.00 F
11	1		*FRONT DOOR SIDE MIRROR LH	0.00	0.00	*140.00 F
12	1		*FRONT DOOR SIDE MIRROR COVER LH	0.00	0.00	*65.00 F
13	1		*REAR DOOR LH	0.00	0.00	*980.00 F
14	1		*REAR DOOR OUTER MOULDING LH	0.00	0.00	*100.00 F
15	1		*REAR DOOR RUBBER LH	0.00	0.00	*85.00 F
16	1		*CENTRE PILLAR GARNISH LH	0.00	0.00	*125.00 F

F=Franchise part.

Sub Total (\$\$)	3,155.00
+ Margin on L,N Items 10.00% (\$\$)	315.50
Total Parts (\$\$)	3,470.50

Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	1,200.00
Labour Items			
2	TO CHECK WIRING SYSTEM	New	50.00
3	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	100.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	820.00
Gross Labour Cost (\$\$)			2,170.00

Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >