

FFS Motor

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
VEHICLE NO. : SKF6234R
ACCIDENT DATE : 30-06-2022 10:00
THIRD PARTY REF. : UNKNOWN

INVOICE NO : TEST
DATE : 23-07-2022

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SKF6234R VOLKSWAGEN JETTA

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT FENDER LH	300.00
1	FRONT FENDER VERTICAL GARNISH LH	20.00
1	FRONT DOOR LH	850.00
1	FRONT DOOR HINGE TOP LH	55.00
1	FRONT DOOR HINGE LOWER LH	55.00
1	FRONT DOOR Seal LH	90.00
1	FRONT DOOR OUTER MOULDING LH	60.00
1	FRONT DOOR SIDE MIRROR HOUSING LH	220.00
1	FRONT DOOR SIDE MIRROR COVER LH	90.00
1	REAR DOOR OUTER MOULDING LH	75.00
		1815.00
ADD 10 %		181.50
TOTAL (A)		
		1996.50

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	20.00
1	TO TRANSFER DOOR MECHANICIM TO NEW DOOR	30.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS	800.00
1	SPRAYPAINTING CHARGES	1000.00

1/2

VEHICLE NO. : SKF6234R
ACCIDENT DATE : 30-06-2022 10:00
THIRD PARTY REF. : UNKNOWN

QTY PARTS DESCRIPTION

	<u>AMOUNT (SG\$)</u>
TOTAL (D)	1,850.00
TOTAL REPAIR COST :	3846.50
EXCESS :	(600.00)
GST :	227.26
	<u>3473.76</u>

2/2

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jul 2022)

Parts: 143 VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT FENDER LH	DT	0.00	0.00	*230.00 F 300
2	1		*FRONT FENDER VERTICAL GARNISH LH	DT	0.00	0.00	*85.00 F 20
3	10		*FRONT FENDER SHIELD CLIP	NN X	0.00	0.00	*55.00 F
4	1		*FRONT DOOR LH	DT	0.00	0.00	*850.00 F
5	1		*FRONT DOOR HINGE TOP LH	SHF	0.00	0.00	*45.00 F 55
6	1		*FRONT DOOR HINGE LOWER LH	SHF	0.00	0.00	*65.00 F 55
7	1		*FRONT DOOR CHECKER LH	NN X	0.00	0.00	*55.00 F
8	1		*FRONT DOOR TOP MOULDING LH SEAL OUTER LH	SJC X	0.00	0.00	*110.00 F 90
9	1		*FRONT DOOR OUTER MOULDING LH	Nec	0.00	0.00	*65.00 F 60
10	1		*FRONT DOOR OUTER HANDLE LH	NN X	0.00	0.00	*100.00 F
11	1		*FRONT DOOR SIDE MIRROR LH	CYA	0.00	0.00	*140.00 F 220
12	1		*FRONT DOOR SIDE MIRROR COVER LH	CYA	0.00	0.00	*65.00 F 90
13	1		*REAR DOOR LH	X	0.00	0.00	*980.00 F
14	1		*REAR DOOR OUTER MOULDING LH	NCL	0.00	0.00	*100.00 F 75
15	1		*REAR DOOR RUBBER LH	SJC	0.00	0.00	*85.00 F
16	1		*CENTRE PILLAR GARNISH LH	SJC X	0.00	0.00	*125.00 F

F=Franchise part.

Sub Total (\$\$) 3,155.00
+ Margin on L,N Items 10.00% (\$\$) 315.50
Total Parts (\$\$) 3,470.50

Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	1000 New	1,200.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	20 New	50.00
3	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	30 New	100.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL WELD CUT PANEL BEAT AND FITTING NEW PARTS	800 New	820.00
Gross Labour Cost (S\$)			2,170.00

Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan@Lkhauto-low
82235769
5/7/22 1700
PIP 6days
not authorise

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: