

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0254/22

DATE : 02-JUL-2022

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS CINDY GOH
ADDRESS : 132 MIMOSA CRESCENT

S(808075)
TELEPHONE NO : 96312664

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 7210015438
VEHICLE NO : SMX6746L
MODEL CODE : FDWARV9P15HDA-D---
MODEL/YEAR : KICKS 1.2L E-POWER PREMIUM PLUS
ENGINE NO : HR12361274C
CHASSIS NO : MNTFEAP15Z0000877
MILEAGE : 45932 KM
DATE IN : 02/07/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 01/07/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

-9045 0084 elmur@fanchong.com
not Authorized
ELMUR
04/07/22
take photo before painting
6 days.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMX6746L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
			390	
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR & BOTH RR FNDR RENEW REAR END PANEL, HATCHBACK DOOR & RR BUMPER	2340.00	1560
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1800.00	1000
3	ZZ/003	APPLY SEALANT TO REAR END PANEL AND HATCHBACK DOOR	200.00	✓
4	ZZ/004	REMOVE AND INSTALL REAR WINDSCREEN GLASS	220.00	✓
5	ZZ/005	REMOVE AND INSTALL REVERSE CAMERA	150.00	✓
6	ZZ/006	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	120.00	✓
7	ZZ/007	RENEW REVERSE SENSOR	150.00	110
8	ZZ/008	RENEW LH RR COMB LAMP & HATCHBACK DOOR LAMP CHECK & INSPECT RH RR COMB LAMP REPLACE IF DAMAGE	88.00	48
9	ZZ/009	SUPPLY REAR LICENSE PLATE		
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	180.00	120
11	ZZ/10	PERFORM RUSFT PROOFING TREATMENT TO TRUNK FLOOR AND REAR END PANEL \$120.00 PER PANEL	240.00	✓
TOTAL LABOUR CHARGES			5488.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX6746L

DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMAR
1	LH RR FENDER WHEEL ARC MOULDING	93829-5RF0A	11 407.20	X
2	WEATHER STRIP HATCHBACK DOOR	90830-5RY0A	11 75.80	X
3	CLIP RR BUMPER @SGD\$ 15.40 EACH	01553-1HA0A	1er 30.80	—
4	RH REFLECTOR RR BUMPER	26565-8990B	11 66.90	X
5	LH REFLECTOR RR BUMPER	26560-8990B	11 66.90	X
6	RH RR HATCHBACK DOOR LAMP	26550-5RY0B	11 246.60	X
7	RH RR COMB LAMP	26550-5RY0A	11 867.80	X
8	LH RR HATCHBACK DOOR LAMP	26555-5RY0B	11 246.60	X
9	LH RR COMB LAMP	26555-5RY0A	1er 867.80	2 ✓
10	REVERSE SENSOR @SGD\$250.40 EACH	28438-4CL0B		su 1001.60 X
11	REVERSE SENSOR COVER BRACKET @SGD\$31.30 EACH	28533-6CA0C		1er 125.20 ✓
12	REAR LICENCE PLATE	RLP		scr 60.00 ✓
13	SUNDRIES	NPN		11 50.00 X
14	EMBLEM - PREMIUM PLUS	84890-PREMIUM		1er 40.00 —
15	REAR W/SCREEN SEALANT	SEALANT - 4		1er 80.00 —
16	EMBLEM-BACK DOOR E POWER	90893-5RY0A	1er 127.10	—
17	ORNAMENT-BACK DOOR KICK	90892-5RB0A	1er 70.00	—
18	HATCHBACK DOOR	K010M-5RYMA	1.65.00 673.90	—
19	HATCHBACK DOOR LOCK	90331-00Q0B	scr 126.50	X
20	RH SIDE BRACKET RR BUMPER	85220-5RF0A	11 70.20	X
21	LH SIDE BRACKET RR BUMPER	85221-5RF0A	3er 70.20	—
22	STAY-RR BUMPER @SGD\$107.70 EACH	H5212-1HJMA	3er 209.40	2 ✓
23	ENERGY ASBORBER RR BUMPER	85090-5RY0A	7er 84.70	2 ✓
24	CROMMET-SCREW RR BUMPER @ SGD\$2.90 EACH	63846-5V000	1er 11.60	—
25	REAR BUMPER	85022-5RJ0H	Dis 591.60	—

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX6746L

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMAR
26	RH RR FENDER INNER TRIM FINISHER	84950-5RY0A	11 96.00	X
27	LH RR FENDER INNER TRIM FINISHER	84951-5RY0A	11 96.00	X
28	CARPET-LUGGAGE TRUNKFLOOR	84904-5RY0A	11 314.50	X
29	BOX-LUGGAGE TRUNKFLOOR	84975-5RY0A	70 268.40	X
30	PLATE LUGGAGE REAR GARNISH	84992-5RY0A	61 90.40	X
31	REAR END PANEL	G9100-5RYAA	Body 407.50	X
SUB TOTAL			6184.40	0.00 1356.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1236.88	0.00 0.00
GRAND TOTAL			4947.52	0.00 1356.80
OVERALL TOTAL			6304.32	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMX6746L

TOTAL LABOUR CHARGES	5488.00
TOTAL SPARE PARTS CHARGES	6304.32

GRAND TOTAL	11792.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

AUTOLUTION INDUSTRIAL PTE. LTD.

SURVIVOR MARCUS
6 DAYS

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0254/22

DATE : 02-JUL-2022

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD

#17-00 TOWER BLOCK

MND COMPLEX S(069110)

TEL : 62239433

FAX : 62234190

ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS CINDY GOH

ADDRESS : 132 MIMOSA CRESCENT

S(808075)

TELEPHONE NO : 96312664

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 7210015438

VEHICLE NO : SMX6746L

MODEL CODE : FDWARV9P15HDA-D---

MODEL/YEAR : KICKS 1.2L E-POWER PREMIUM PLUS

ENGINE NO : HR12361274C

CHASSIS NO : MNTFEAP15Z0000877

MILEAGE : 45932 KM

DATE IN : 02/07/2022

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 01/07/2022

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMX6746L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR & BOTH RR FNDR RENEW REAR END PANEL, HATCHBACK DOOR & RR BUMPER	2340.00	1560.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1800.00	1000.00
3	ZZ/003	APPLY SEALANT TO REAR END PANEL AND HATCHBACK DOOR	200.00	200.00
4	ZZ/004	REMOVE AND INSTALL REAR WINDSCREEN GLASS	220.00	220.00
5	ZZ/005	REMOVE AND INSTALL REVERSE CAMERA	150.00	150.00
6	ZZ/006	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	120.00	120.00
7	ZZ/007	RENEW REVERSE SENSOR	150.00	110.00
8	ZZ/008	RENEW LH RR COMB LAMP & HATCHBACK DOOR LAMP CHECK & INSPECT RH RR COMB LAMP REPLACE IF DAMAGE	88.00	48.00
9	ZZ/009	SUPPLY REAR LICENSE PLATE		
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	180.00	120.00
11	ZZ/012	TO APPLY NANO CERAMIC COATING ON THE HATCHBACK DOOR, LEFT REAR FENDER, AND REAR BUMPER	220.00	220.00 (A)
12	ZZ/10	PERFORM RUSFT PROOFING TREATMENT TO TRUNK FLOOR AND REAR END PANEL \$120.00 PER PANEL	240.00 240.00	240.00 ✓
TOTAL LABOUR CHARGES			5708.00	3988.00

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX6746L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMA
1	CLIP RR BUMPER @SGD\$ 15.40 EACH	01553-05933	30.80		OK
2	LH RR COMB LAMP	26555-5RY0A	867.80		OK
3	REVERSE SENSOR COVER BRACKET @SGD\$31.30 EACH	28533-6CA0C		125.20	OK
4	REAR LICENCE PLATE	RLP		60.00	OK
5	EMBLEM - PREMIUM PLUS	84890-PREMIUM		40.00	OK
6	EMBLEM-BACK DOOR E POWER	90893-5RY0A	127.10		OK
7	ORNAMENT-BACK DOOR KICK	90892-5RB0A	70.00		OK
8	HATCHBACK DOOR	K010M-5RYMA	673.90		OK
9	REAR W/SCREEN SEALANT	SEALANT - 4		80.00	OK
10	LH SIDE BRACKET RR BUMPER	85221-5RF0A	70.20		OK
11	STAY-RR BUMPER @SGD\$107.70 EACH	H5212-1HJMA	209.40		OK
12	ENERGY ASBORBER RR BUMPER	85090-5RY0A	84.70		OK
13	CROMMET-SCREW RR BUMPER @ SGD\$2.90 EACH	63846-5V000	11.60		OK
14	REAR BUMPER	85022-5RJ0H	591.60		OK
15	BOX-LUGGAGE TRUNKFLOOR	84975-5RY0A	268.40		OK
16	PLATE LUGGAGE REAR GARNISH	84992-5RY0A	90.40		OK
17	REAR END PANEL	G9100-5RYAA	407.50		OK
SUB TOTAL			3503.40	0.00	305.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			700.68	0.00	0.00
GRAND TOTAL			2802.72	0.00	305.20
OVERALL TOTAL			3107.92		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMX6746L

NETT ITEM 3503.40
LESS 20.00%) -700.68
NETT AMOUNT 2802.72

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 305.20
LESS .00%) 0.00
SPECIAL NETT AMOUNT 305.20

TOTAL LABOUR CHARGES 3988.00
TOTAL SPARE PARTS CHARGES 3107.92

TOTAL CHARGES 7095.92
ADD 7 % GST 496.71

GRAND TOTAL 7592.63
