

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22006332/GCY3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000608	
Claimant Vehicle No :	SHB4333H	Insured Vehicle No :	MID35391	
Date of Loss:	28/06/2022	Nature of Claim:	TP	Claim No: M2203453

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4333H	Engine No:	2ZR2F99117
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU603090249
Reg. Date:	13/12/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,369.53	233.27	2,136.26	90.16
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,180.00	1,395.00	785.00	36.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,560.53	1,639.27	2,921.26	64.06
+ GST 7.00/7.00% (S\$)	319.24	114.75	204.49	64.06
Nett Amount (S\$)	4,879.77	1,754.02	3,125.75	64.06

INSPECTION

Date of Assignment:	04/07/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	01/07/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB4333H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PANEL LH	Repair	1,258.30 FL	*- FL
2	1		*REAR ROCKER GARNISH LH	Repair	576.00 FL	*- FL
3	1		*REAR FENDER LH	Repair	992.04 FL	*- FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*REAR WHEEL COVER LH	Scratched	177.70 FL	*177.70 FL
6	1		*REAR DOOR COMFORT LOGO APP	Necessary	80.00 FS	*80.00 FS
7	1		*PETROL STCKER LID	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,126.04	277.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	756.51	44.43
Total Parts (\$\$)	2,369.53	233.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,050.00	525.00
2	SPRAY PAINTING	New	800.00	750.00
3	REMOVE/REFIX UPHOLSTERY REAR	New	90.00	60.00
4	REMOVE/REFIX DOPR PART	New	90.00	60.00
5	CHECK LIGHTING AND WIRING	New	60.00	0.00
6	TUFF COATING	New	90.00	0.00
Gross Labour Cost (\$\$)			2,180.00	1,395.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >