

ASS. REC. BY:

REF:

GRB/22006337/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☒	☒

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBN8265R

Yr Regn:

11/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400

c.c.

399

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

6835P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NC42

1901162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

120/60R17

R:

160/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

29/6/22

D.O.I.

4/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

& N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Res EM not ready, No GIA yet

19/7

6/12pm @ 3700L Can't Rose

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 6 July 2022

To : LKK

Attn : Mr Kenneth

Tel: 96910663

VEHICLE NO : FBN 6265R

ACCIDENT DATE: 29/June/ 2022

onda CB400SF ABS MANUAL

*Not Withain
11pm 83700h
Resurvey After Paint
4 days*

Description	Qty	Quotation \$
1 Rear Mudguard <i>245</i>	1	<i>Am</i> 280.00 ✓
2 Tail Panel	1	<i>scn</i> <i>R</i> 230.00 X
3 Exhaust Pipe <i>1240</i>	1	<i>R</i> 1,500.00 ✓
4 Rear Box GIVI <i>245</i>	1	<i>nd/w</i> 350.00 ✓
5 Side Box RH	1	<i>cm</i> 280.00 ✓
6 Side Box LH	1	<i>cm</i> 280.00 ✓
7 Crash Bar	1 set	<i>nd</i> 320.00 ✓
8 Handle Bar <i>180</i>	1	<i>R</i> 290.00 ✓
9 Visor <i>215</i>	1	<i>cm</i> 280.00 ✓
10 Clutch Lever	1	<i>nd</i> 90.00 ✓
11 Fork Tube	1	<i>R</i> 1,200.00 X
12 Brake Lever	1	<i>R</i> 95.00 X
13 Belly Pan	1	<i>cm</i> 350.00 ✓
14 Exhaust Guard	1	<i>nd</i> 290.00 ✓
15 Mirror LH <i>160</i>	1	<i>nd/w</i> 190.00 ✓
16 Headlamp Assy (Stanley) <i>565</i>	1	<i>nd/w</i> 1,250.00 ✓
17 Rear Signal RH	1	<i>R</i> 190.00 X
18 Tai light <i>253</i>	1	<i>cm</i> 280.00 ✓
Sub-Total		7,745.00
Less 10%		774.50
Sub-Total		6,970.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : FBN 6265R

Honda CB400

Nett items

- 1 Rear Number Plate
- 2 IU UNIT
- 3 Towing Fee
- 4 Remove and replace Necessary Parts, Align etc
- 5 Remove and replace fork tube Supply fork Oil
and replace Exhaust Pipe

Rt 18.00 ✓
Dd 170.00 ✓
40.00 *351*
250.00 *1501*
un 180.00 X

Sub-Total

658.00

Nett Total

7,628.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD