



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET			Ref: CC4/ASM22006343/Apa3q2 Date: 13/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 1059X	Veh. Inspected	SLP 7204G
	Policy No.	GA610755	Coverage (\$)	0.00
	Claim No.	S2M045SG	Excess (\$)	0.00
	Assign From		Assign Date	04/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	ACR500072876	Colour	BLACK
	Odometer	154073 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	MICHELIN	6 mm
	L/H Front Tyre	235/50 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/50 R18	MICHELIN	6 mm
	L/H Rear Tyre	235/50 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/07/2022	Inspection Date	04/07/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	