



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22006348/Kvy3m4	
			Date: 22/07/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4739R	Veh. Inspected	SMF 139Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/22/2082	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	04/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053BK4107036000	Colour	METALLIC GOLD
	Odometer	256390 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	8 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/06/2022	Inspection Date	04/07/2022
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	