



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI22006353/Uqy3m4 Date: 13/07/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 2440H	Veh. Inspected	SJT 127U
Policy No.		Coverage (\$)	0.00
Claim No.	D220001994MSH	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	04/07/2022
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN NEW GOLF (A)	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WVWZZZ1KZAW005921	Colour	WHITE
Odometer	388636 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	7 mm
L/H Front Tyre	225/40 R18	GOODYEAR	7 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	7 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/06/2022	Inspection Date	04/07/2022
Survey held at	15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	