



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: ONG KIAN THENG DERICK		Ref: CS/ASM22006355/Tvy3e2 Date: 27/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMZ 4311K	Veh. Inspected	FBR 8450M
Policy No.	GA571836	Coverage (\$)	0.00
Claim No.	S2M045MZ	Excess (\$)	0.00
Assign From	ONG KIAN THENG DERICK	Assign Date	04/07/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA XMAX300	c.c	292
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	MH3SH0848LK013176	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70 R14	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R14	PIRELLI	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/06/2022	Inspection Date	05/07/2022
Survey held at	GUSTO BROZ PTE LTD 25 KAKI BUKIT ROAD 4, #01-35, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	