LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01

Singapore 068897

From: LKK Auto Consultants Pte Ltd

> 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Sharon Lim 15 Jul 2022 Attn: Date:

Preliminary Advice

Vehicle No : SML8310K Accident Date : 29/06/2022 Make : TOYOTA CAMRY Policy No. : SP2001918221 Excess Assignment Date : 04/07/2022 : S\$600.00

Date of Inspection : 5/7/2022 Est. Duration of Repair :5

Inspection At :SME MOTOR PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,812.00 (Incl. supplementary
-----------------------------	------	-------------------------------

\$1003.00)

Revised Amount :S\$ 6,291.30 Check Items (Estimated) 40.00 :S\$

6,331.30 (incl.supplementary \$1003.00) Total :S\$

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value 120,000.00 :S\$ COE / PARF Rebate :S\$ 46,344.00

Salvage Value :S\$

Margin for Repair :S\$ 73,656.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Part by part repair. According to repairer there is no 2nd hand parts available.

Kindly approved on the supplementary