## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01

Singapore 068897

From: LKK Auto Consultants Pte Ltd

> 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Sharon Lim 05 Jul 2022 Attn: Date:

# **Preliminary Advice**

Vehicle No : SML8310K Accident Date : 29/06/2022 Make : TOYOTA CAMRY Policy No. : SP2001918221 Excess : S\$600.00 Assignment Date : 04/07/2022

Date of Inspection : 5/7/2022 Est. Duration of Repair : 4

: SME MOTOR PTE LTD Inspection At

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,809.00
Revised Amount	:S\$	4,411.80
Check Items (Estimated)	:S\$	504.20
Total	:S\$	4,916.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$

Pre-Accident Value 120,000.00 :S\$ COE / PARF Rebate 46,344.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 73,656.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

- ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments: Part by part repair. According to repairer there is no 2nd hand parts available.
  - . Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.