

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

(SUPPLEMENTARY)

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD-330 (07)
Policy No:	SP2001918221	Date of Loss:	29/06/2022
Vehicle Reg. No.:	SML8310K	Driveable?	
Driver Age/Info:	50	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KOK MUN LOONG	Contact No:	+6596689110
Driver:	KOK MUN LOONG		
Make/Model:	TOYOTA CAMRY, 2.5 (A)	Vehicle Reg. Date:	06/06/2019
Vehicle Colour:	WHITE		
Engine No:	A25A5071140	Chassis No:	JTNB23HK803017228
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	583.00
Miscellaneous Items	20.00
Labour	400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	1,003.00
+ GST 7.00% (\$)	70.21
Nett Amount (\$)	1,073.21
+ Previous Estimates (\$)	8,355.63
Claim Total (\$)	9,428.84

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)**Parts:** 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SML8310K/14/07/2022 15:21**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR BUFFER <i>To. n</i>	0.00	0.00	*245.00 F ✓
2	1		*FRT BUMPER REINFORCEMENT BRACKET LH <i>nn</i>	0.00	0.00	*55.00 F ✓
3	1		*AIRCON SIDE DEFLECTOR LH <i>To. n</i>	0.00	0.00	*85.00 F ✓
4	1		*LH HEADLAMP PANEL <i>Self</i>	0.00	0.00	*145.00 F ✓

F=Franchise part.

Sub Total (\$\$) **530.00****+ Margin on L,N Items 10.00% (\$\$)** **53.00****Total Parts (\$\$)** **583.00****SME Motor Pte Ltd/SML8310K/14/07/2022 15:21. Not valid without Reference section.**Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 RADIATOR COOLANT

NA

20.00

Sub Total (S\$)

20.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 REPLACE AND SPRAY FRT LH CHASIS JOINT AND REPAIR CHASIS

New

300.00

2 REMOVE AND REFIX AIRCON AND GAS

New

100.00

Gross Labour Cost (S\$)

400.00

SME Motor Pte Ltd/SML8310K/14/07/2022 15:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >