

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
 Singapore 737856
 Tel: Fax: Email:

INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	
Policy No:	5106383818-03	Date of Loss:	24/06/2022
Vehicle Reg. No.:	GBJ1118L	Driveable?	no
Driver Age:		Third Party Vehicle No.:	GBE7130L
Any Injuries?	no	Contact No:	
Insured/Claimant:	A.L.3 CONSTRUCTION PTE. LTD.	Driver:	HO KENG SIONG

PARTS MODEL

Make/Model:	Toyota, DYNA - JTFNT24Y	Vehicle Reg. Date:	02/01/2019
Vehicle Colour:		Engine Number:	
Chassis No:	JTFAT35YX0K211911	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Collision - Head to Rear
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	3,325.28
Miscellaneous Items	165.00
Labour	1,890.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total(S\$):	6,380.27
GST 7.00%(S\$):	446.62
Nett Amount(S\$):	6,826.89

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged parts and resurvey
- Parts prices are based on confirmation
- Third party settlement on "Without Prejudice" basis
- No illegal modification to the vehicle
- Supplementary documents to be provided and
 is subject to final approval by the Insurance Company

Acknowledged:

Signature:

Date:

TAILS**On Parts**

Qty	Particulars	Amount	%Disc	After Disc
1	REAR EXHAUST PIPE X	1,050.00	-25.00	787.50
1	REAR EXHAUST PIPE MOUNTING X <i>Sum</i>	55.00	-10.00	49.50
3	REAR TAILLAMP LH X	292.50	-10.00	263.25
4	REAR TAILLAMP RH X <i>Cut</i>	292.50	-10.00	263.25
5	REAR TAILBOARD <i>fine</i>	1,137.70	-25.00	853.28
6	REAR TAILBOARD TOYOTA EMBLEM <i>MC</i>	85.00	-10.00	76.50
7	REAR TAILBOARD BOTTOM LOCK LH <i>BT</i>	115.00	-10.00	103.50
8	REAR TAILBOARD BOTTOM LOCK RH <i>BT</i>	115.00	-10.00	103.50
9	REAR FLOOR PANEL X <i>NN</i>	1,100.00	-25.00	825.00

Total Parts (\$\$) 3,325.28

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE <i>BT</i>	45.00	0.00	45.00
2	1	REAR 70KM/H STICKER <i>Sum</i>	60.00	0.00	60.00
3	1	REAR 6 PAX STICKER	60.00	0.00	60.00

Sub Total (\$\$) 165.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
2	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 X <i>Sum</i>
3	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	280.00	0.00	280.00 X <i>Sum</i>
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,500.00	0.00	1,500.00 <i>200</i>

Gross Labour Cost (\$\$) 1,890.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,000.00	0.00	1,000.00 <i>300</i>

Gross Labour Cost (\$\$) 1,000.00

< END OF ESTIMATES >

3 Days

ump Sum Repair

After repair photos

Guo Qiang

8288 0282

5/7/22