



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22006368/Ucy3m4	
			Date: 22/07/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 9696S	Veh. Inspected	SKP 8221L
	Policy No.	D-22099203MFCV\75	Coverage (\$)	0.00
	Claim No.	D22001987MFCV	Excess (\$)	0.00
	Assign From	JOANNE TAN JO ANN	Assign Date	04/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA SORENTO (A)	c.c	2359
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	KNAKU816ME5575976	Colour	BROWN
	Odometer	78893 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	PIRELLI	6 mm
	L/H Front Tyre	235/55 R19	PIRELLI	6 mm
	R/H Rear Tyre	235/55 R19	PIRELLI	6 mm
	L/H Rear Tyre	235/55 R19	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/06/2022	Inspection Date	05/07/2022
	Survey held at	JEMENTAH MOTOR WORKS BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	