

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006369/TQY3Q2**Date:** 03/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00005662200
Claimant Vehicle No :	SHB8075B	Insured Vehicle No :	GBC111Z
Date of Loss:	02/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204629/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8075B	Engine No:	D4FDFH314409
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5658265
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	640819 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,674.90	577.50	2,097.40	78.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	700.00	1,410.00	66.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,784.90	1,277.50	3,507.40	73.30
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	4,784.90	1,000.00	3,784.90	79.10
+ GST 7.00/7.00% (S\$)	334.94	70.00	264.94	79.10
Nett Amount (S\$)	5,119.84	1,070.00	4,049.84	79.10

INSPECTION

Date of Assignment:	04/07/2022	
Date Inspected:	05/07/2022	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8075B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEAD LAMP	Not Necessary	1,028.00 FL	*- FL
2	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
3	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
4	2		*FRONT BUMPER N/S & O/S SIDE RETAINER	Not Necessary	32.00 FL	*- FL
5	2		*FRONT BUMPER N/S & O/S UPPER BRACKET	Not Necessary	32.00 FL	*- FL
6	2		*FRONT BUMPER N/S & O/S SUPPORT BRACKET	Not Necessary	32.00 FL	*- FL
7	1		*FRONT BUMPER N/S PROTECTOR	Not Necessary	51.00 FL	*- FL
8	1		*FRONT BUMPER N/S FOG LAMP COVER	Not Necessary	66.00 FL	*- FL
9	1		*BONNET GRILLE	Not Necessary	385.00 FL	*- FL
10	1		*FRONT N/S FENDER	Repair	384.00 FL	*- FL
11	1		*FRONT N/S FENDER INNER SHIELD	Not Necessary	120.00 FL	*- FL
12	1		*FRONT N/S WHEEL COVER	Not Necessary	116.00 FL	*- FL
13	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
14	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
15	1		*FRONT N/S FENDER STICKER	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,957.00	635.00
- List Item Discount on L Items 10.00/10.00% (\$)	282.10	57.50
Total Parts (\$)	2,674.90	577.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
2	TO DISMANTLE AND REPLACE FRONT N/S UNDERCARRIAGE	New	250.00	0.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE FRONT N/S WHEEL HOUSE ETC	New	800.00	300.00
5	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,FRONT N/S WHEEL HOUSE	New	600.00	400.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	0.00
Gross Labour Cost (\$\$)			2,110.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >