

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Jul-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8075 B

1 pc	Front n/s head lamp	\$ 1,028.00 X nn
1 pc	Front bumper emblem	\$ 44.00 nn
1 pc	Front bumper	\$ 531.00 de
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$ o/s ⁿⁿ 32.00 n/s ⁿⁿ
2 pcs	Front bumper n/s & o/s upper bracket @ \$16.00	\$ o/s ⁿⁿ 32.00 n/s ⁿⁿ
2 pcs	Front bumper n/s & o/s support bracket @ \$16.00	\$ o/s ⁿⁿ 32.00 n/s ⁿⁿ
1 pc	Front bumper n/s protector	\$ 51.00 X
1 pc	Front bumper n/s fog lamp cover	\$ 66.00 X } ⁿⁿ
1 pc	Bonnet grille	\$ 385.00 X }
1 pc	Front n/s fender	\$ 384.00 Rp
1 pc	Front n/s fender inner shield	\$ 120.00 X nn
1 pc	Front n/s wheel cover	\$ 116.00 X nn

575
10/2 - 517.50

\$ 2,821.00

Less 10%

\$ 282.10

\$ 2,538.90

S/NETT

1 set	Front n/s fender inner shield clips
1 set	Front bumper clips
1 pc	Front n/s fender sticker

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To check wheel alignment

To dismantle and replace front n/s undercarriage

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s wheel house etc

To putty and spray painting on Front bumper, front n/s fender, front n/s wheel house,

To apply rustproofing on the repaired and replaced panels.

\$ 28.00 ~~X~~ nn
\$ 48.00 ~~3one~~
\$ 60.00 ~~nn~~ 30
60

\$ 80.00 ~~X~~ }
\$ 250.00 ~~X~~ } ⁿⁿ
\$ 180.00 ~~X~~ }

\$ 800.00 300

\$ 600.00 400

\$ 200.00 ~~nn~~

\$ 4,784.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Tanphui 27495749
10/5/22 2420 pm
4/5 Rem after repair
tamphui@lkkauto.com