

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIN SHIXIANG
BLK 128 RIVERVALE STREET #11-828
SINGAPORE 540128

Contact : 88796349

TP Budget Priced.
Online.

TAX INVOICE

Repair Code : CLM15580

Date in : 02/07/2022

Vehicle Num. : SNC1514X

Model : TOYOTA HARRIER M GARDE

Chassis/Eng# : JTEZB3GH80J005158/8ARZ175478

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	1453.00	<i>1350</i> 1453.00
<i>Φ</i> REAR BUMPER END SEAL COVER L/R <i>Damaged</i>	2	139.70	279.40 ✓
REAR BUMPER LOWER LID <i>Rehd</i>	1	422.90	422.90 ✓
REAR BUMPER REFLECTOR L/R <i>Lit cend</i>	2	59.80	<i>5580</i> 119.60 <i>SS</i>
REAR BUMPER REINFORCEMENT <i>Best</i>	1	1364.00	<i>1080</i> 1364.00
REAR BUMPER REVERSE SENSOR <i>2 pieces dnd</i>	4	215.00	<i>430</i> 860.00
REAR BUMPER REVERSE SENSOR HOLDER <i>Nu</i>	4	68.00	<i>100</i> 272.00
REAR BUMPER SIDE RETAINER L/R <i>Nu</i>	2	82.70	<i>X</i> 165.40
REAR BUMPER SPONGE <i>Cend</i>	1	112.40	<i>✓</i> 112.40
REAR END PANEL <i>Rejs</i>	1	821.10	<i>X</i> 821.10
REAR LH TAILLAMP <i>3 Nu</i>	1	492.50	<i>X</i> 492.50
REAR LH TAILLAMP LOWER BRACKET <i>3 Nu</i>	1	121.10	<i>X</i> 121.10
REAR TAILGATE <i>Rejs</i>	1	2126.40	<i>X</i> 2,126.40
REAR TAILGATE 'HARRIER' EMBLEM <i>3 Nu</i>	1	73.70	<i>✓</i> 73.70
REAR TAILGATE 'LOGO' EMBLEM <i>3 Nu</i>	1	57.30	<i>✓</i> 57.30
REAR TAILGATE 'TURBO' EMBLEM <i>3 Nu</i>	1	68.00	<i>✓</i> 68.00
REAR TAILGATE WEATHER STRIP <i>3 Nu</i>	1	441.30	<i>X</i> 441.30
REAR TAILGATE WINDSCREEN MOULDING <i>3 Nu</i>	1	177.90	<i>X</i> 177.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LIN SHIXIANG
 BLK 128 RIVERVALE STREET #11-828
 SINGAPORE 540128

Contact : 88796349

TAX INVOICE

Repair Code : CLM15580

Date in : 02/07/2022

Vehicle Num. : SNC1514X

Model : TOYOTA HARRIER M GARDE

Chassis/Eng# : JTEZB3GH80J005158/8ARZ175478

Subtotal before discount 9,428.00

Percentage discount 25%

Sub-total 1

REAR BUMPER CLIPS - SET

1

50.00

30 50.00

REAR TAILGATE INNER TRIM BOARD CLIPS - SET

1

50.00

X 50.00

REAR TAILGATE WINDSCREEN SEALANT

1

80.00

X 80.00

Subtotal before discount

180.00

Percentage discount 0%

Sub-total 2

180.00

Parts-total

7,251.00

LABOUR

To reset system after repair works

X 400.00

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

50 80.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

X 100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

990

500 1,000.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400 1,000.00

To apply anti-rust chemical on repaired and replaced panel.

400 120.00

To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.

X 80.00

Labour Total

2,780.00

Parts & Labour Total

10,031.00

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5 04/07/22

04 Days.

Total: 4045.12
 4/5: 3.2K ✓