

Case Details

Case Reference Number :

TAX/07/22/2003

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB1167R

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18703-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 01/07/2022 12:22 PM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			GRILLE-FRT BPR FASCIA LOWER	1	149.03	149.03	10.00	134.13	Replace	0	0	Check	? Xan
Standard	Main			FINISHER-FRT BPR LOWER - LH	1	20.38	20.38	10.00	18.34	Replace	0	0	Not Give	Xan
Standard	Main			COVER-FRT FOG LP - LH	1	40.24	40.24	10.00	36.22	Replace	1	36.22	Replace	ca
Standard	Main			FINISHER-FRT FOG LP CVR - LH	1	47.32	47.32	10.00	42.59	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET-FRT BPR FASCIA - LH	1	23.08	23.08	10.00	20.77	Replace	0	0	Check	? Xan
Standard	Main			FINISHER-FRT BPR - LH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Give	Xan
Standard	Main			PANEL ASM-LEG CTHR	1	131.04	131.04	10.00	117.94	Replace	0	0	Not Give	Xan
Standard	Main			BAR ASM-FRT BPR IMP	1	624.00	624.00	10.00	561.60	Replace	0	0	Not Give	Xan
Standard	Main			GRILLE ASM-RAD	1	978.02	978.02	10.00	880.22	Replace	0	0	Not Give	Xan
Standard	Main			HEADLAMP ASM -LH	1	1,098.86	1,098.86	10.00	988.97	Replace	1	988.97	Replace	ca
Standard	Main			FENDER ASM-FRT - LH	1	379.80	379.80	10.00	341.82	Replace	1	0	Repair	P

Total Spare Part Cost 3,993.71

Lump Sum Discount (%) 0.00

Final Spare Part Cost 3,993.71

Surveyor Total 1,787.38

Lump Sum Dis (%) 0

Final Sur Total 1,787.38

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			LINER ASM-FRT W/H - LH	1	125.22	125.22	10.00	112.70	Replace	1	112.70	Replace v	ser ✓
One Time Key In	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	1	649.49	Replace v	de -
Total Spare Part Cost									3,993.71	Surveyor Total		1,787.38		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									3,993.71	Final Sur Total		1,787.38		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	1,200.00	300.00	
Total:			1,200.00	300.00 /	


Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	220	
2	Main	TO RESPRAY FRONT FENDER LH	428.00	220	
Total:			856.00	440.00 /	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00 XM	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0.00 XM	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 XM	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0.00 XM	
5	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00	
6	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			880.00	300.00 /	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,993.71	1,787.38
Total Labour Cost	1,200.00	300.00
Total Spray Painting	856.00	440.00
Other	880.00	300.00
Overall Total	6,929.71	2,827.38
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	2,827.38
Surveyor Approved Amount		2,827.38
No of Repair Days*	5	3
Remarks	-	resurvey before & after paint photos, part by part.
Surveyor Name		Rasul
Signature		
Survey Date	04/07/2022	Save Clear