

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22006380/Gqy3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 16/09/2022 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SH 8183K SMV 8246K Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M045UA Excess (\$) 0.00 ANG YVONNE **Assign Date** 05/07/2022 Assign From **Vehicle Particulars & Condition** 2. HONDA FREED HYBRID 1.5 1496 Make & Model c.c HIDDEN 2020 Year of Reg. Engine No. GB73107599 WHITE Chassis No. Colour Odometer 87418 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/65 R15 DUNLOP 6 mm DUNLOP L/H Front Tyre 185/65 R15 6 mm 185/65 R15 DUNLOP R/H Rear Tyre 6 mm **DUNLOP** L/H Rear Tyre 185/65 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 02/07/2022 08/07/2022 ( 11:00 AM ) Inspect Date / Time Accident Date SIN SENG HONG SPRAY PAINTING & SERVICES Survey held at 3023A UBI ROAD 1 #01-63 SINGAPORE 408717 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/ASM22006380/Ggy3m4

**Estimate Days of Repair** 

**Inspected By** 

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

5 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

ESTIMATED NORMAL PERIOD FOR REPAIR:

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.