

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT122006384/Ury3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD4FA

at Workshop m/s: Borneo

of _____

Insured: GSH 8999A

Policy No. DMCVSNW00097692105

Claims No. SNM22D204651/C02/LEWLC

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 5105k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 12 days

Res.: Yes or No

Lum Sum: 113.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: L79546073

Veh No: SLD4FA

Yr Regn: 15/12/20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / Hybrid

Make: Toyota

Yaris cross 1490

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 41954

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKBA3340L002770

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55-R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 03/07/22

D.O.I. 5/7/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear w/Screen shattered

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction Rep 12k.

SG car met NO 2020 model

new car 8145k.

22/8/22

PIR 21939.10 insured sum

(red 10,009.87, 31%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 22/8/22-typist

Report Format : Merimen

Lump Sum / I.B.I. (\$ 21,939.10)

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	540G
Vehicle Details	
Vehicle No.:	SLD48A
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	YARIS CROSS HYBRID ACTIVE (AT) (2WD)
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	M15AY085298
Chassis No.:	JTDKBAB340L002770
Maximum Power Output:	82.0 kW (109 bhp)
Open Market Value:	\$24,007.00
Original Registration Date:	15 Dec 2020
First Registration Date:	15 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$15,610.00 7805
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2030
PARF Rebate Amount:	\$11,707.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,714.00
COE Rebate Amount:	\$34,366.00
Total Rebate Amount:	\$46,073.00

The information contained herein is correct as at 05 Jul 2022

OK



Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

02/2009 Toyota Axio \$53800, \$608 Monthly at 2.99%



\$608 Monthly only! 2.99% By
GV CARS FINANCING, \$0
Downpayment. PHV/Z10
Welcome
GV Automobile Centre StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Sort by 20 results/page

16 vehicles



Toyota Yaris

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Yaris		Any	Any	2021	Any	Any	Any	Available
	Toyota	Yaris Cross Hybrid 1.5A X	\$123,888	\$12,790 /yr	24-Sep-2021	1,490 cc	8,261 km	SUV	Available
Fuel Type: Petrol-Electric One Owner. Ready To View. Toyota Yaris Cross 1.5 Hybrid CVT In Stock Now. 3 Years Warranty. Genuinely Clocked Lowest Mileage 8261... Posted: 02-Jul-2022									
	Toyota	Yaris Cross Hybrid 1.5A G	\$120,000	\$12,660 /yr	15-Jun-2021	1,490 cc	-	SUV	Available
Fuel Type: Petrol-Electric Comes with many active safety and convenient features. Reliable and easy to maintain. Compact in size yet provides a great driving posi... SG Car Choice Pte Ltd Posted: 02-Jul-2022									
	Toyota	Yaris Cross 1.5A G	\$116,800	\$12,600 /yr	24-May-2021	1,490 cc	20,000 km	SUV	Available
1 owner, agent unit. Comes with agent warranty. Great saving from purchasing brand new unit. Sporty white matched maroon red. Com... Hamilton Autohub Pte Ltd Posted: 01-Jul-2022									
	Toyota	Yaris Cross Hybrid 1.5A Excite	\$126,800	\$12,990 /yr	26-Aug-2021	1,490 cc	36,634 km	SUV	Available
Fuel Type: Petrol-Electric Best seller Sep 2021 Toyota Yaris Cross 1.5 Hybrid CVT, Borneo Motors warranty, flexible loan and instalments available. Interested buyer... Edmund Motor Pte Ltd Posted: 26-Jun-2022									
	Toyota	GR Yaris 1.6M Circuit Pack	\$243,800	\$24,760 /yr	25-May-2021	1,618 cc	5,942 km	Sports	Available
Certified Quality Standards. Agent Unit. Agent's 3-Year/100,000 Km Warranty, Service Package Valid Till May 2024. Fully Serviced And M... Republic Auto Posted: 19-Jun-2022									
	Toyota	Yaris Cross Hybrid 1.5A G	\$129,800	\$13,520 /yr	16-Aug-2021	1,490 cc	1,200 km	SUV	Available
Fuel Type: Petrol-Electric 1 careful owner, agent maintained, low depreciation, fuel efficiency, easy financing, flexible loan available, accident free, 6 months free s... SG Car Choice Pte Ltd Posted: 18-Jun-2022									
	Toyota	Yaris Cross 1.5A X	\$103,800	\$10,920 /yr	13-Oct-2021	1,490 cc	30,188 km	SUV	Available
Most stylish crossover ever made by Toyota! Spacious! Superb fuel efficiency! Hassle free maintenance! Single owner and comes with wa... ✓ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More Car House Pte Ltd Posted: 17-Jun-2022									

Compare



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

*not authorized
her way
to high level
policy.
p/p 21939.105/7/22
12 days.*

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153		
			Document No. 0				
			Document Date 04/07/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBAB340L002770		M15AY085298	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-GBH8999A ACC DATE:03/07/2022 DRIVE IN:04/07/2022 DATE-IN:04/07/2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				<i>neu</i> 30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				<i>neu</i> -366.36	
3	S	BP-SUBLET REAR NUMBER PLATE				<i>neu</i> -68.00	
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				<i>neu</i> -180.00	
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				<i>neu</i> -180.00	
6	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				<i>neu</i> -360.00	
7	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE,REAR END PANEL AND REAR LH FENDER				<i>neu</i> 180.00	
8	S	BP-SUBLET REMOVE & INSTALL FUEL TANK TO ASSIST REP AIR				<i>neu</i> X 360.00	
9	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				<i>neu</i> -462.00	
10	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				<i>neu</i> -290.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153
	Document No. 0	
	Document Date 04/07/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKBB340L002770	M15AY085298	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				180.00
12	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				360.00
13	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
14	B	BP-LAB2 REPAIR & REALIGN REAR CHASSIS PANEL				720.00
15	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				5760.00
16	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREA				4720.00
17	1	T52159-5C906 COVER, RR BUMPER	1.00	311.90		311.90
18	2	T52563-52060 RETAINER, RR BUMPER,	1.00	65.00		65.00
19	3	T52576-52210 RETAINER, RR BUMPER	1.00	108.70		108.70
20	4	T52562-52100 RETAINER, RR BUMPER,	1.00	65.00		65.00
21	5	T52575-52230 RETAINER, RR BUMPER	1.00	108.70		108.70
22	6	T52453-52902 GUARD, RR BUMPER,	1.00	541.10		541.10
23	7	L75392-35220 RETAINER, OUTSIDE	4.00	4.30		17.20
24	8	T58307-52750 PANEL SUB-ASSY, BODY	1.00	755.10		755.10
25	9	T58311-52310 PAN, RR FLOOR	1.00	879.90		879.90
26	0	T58316-52230 EXTENSION, RR FLOOR	1.00	74.40		74.40
27	1	T61602-52880 PANEL SUB-ASSY,	1.00	1061.60		1061.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mdm Chia Wey Ching Mabel
	Document No. 0	138 Bishan Street 12 #08-444 Singapore 570138
	Document Date 04/07/2022	Mobile: 98750153

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	2	T61056-52010 PANEL SUB-ASSY, RR <i>Body to R</i>	1.00	95.50	X	95.50 X
29	3	T58387-52060 C0 PLATE, RR FLOOR <i>end panel garnish DUS</i>	1.00	343.90	✓	343.90 ✓
30	4	T58410-52160 B0 BOARD ASSY, DECK <i>LH</i>	1.00	574.10	✓	574.10 ✓
31	5	T64771-52300 B0 COVER, SPARE WHEEL <i>woped</i>	1.00	418.80	✓	418.80 ✓
32	6	T64777-10020 CUSHION, SPARE WHEEL <i>woped/cra</i>	1.00	109.30	X	109.30 X
33	7	T64740-52870 C0 PANEL ASSY, DECK <i>ender inner trim</i>	1.00	642.80	✓	642.80 ✓
34	8	T90467-05164 C7 CLIP <i>ner</i>	4.00	2.40 1.90	✓	9.60 7.60 ✓
35	9	S62940-02200 DUCT ASSY, QUARTER V <i>ner</i>	1.00	80.60	X	80.60 X
36	0	T67005-52E01 PANEL SUB-ASSY, BACK <i>Tailgate Body to</i>	1.00	1543.90	✓	1543.90 ✓
37	1	T67881-52240 WEATHERSTRIP, BACK <i>ner</i>	1.00	354.00	✓	354.00 ✓
38	2	T67751-52220 C0 BOARD, BACK DOOR <i>ner</i>	1.00	318.30	X	318.30 X
39	3	T76827-52070 RETAINER, BACK DOOR <i>ner</i>	1.00	23.40	X	23.40 X
40	4	T68105-52770 GLASS SUB-ASSY, BACK <i>shotted</i>	1.00	1285.80	✓	1285.80 ✓
41	5	T64813-K2020 DAM, BACK WINDOW <i>ner</i>	1.00	22.00	✓	22.00 ✓
42	6	T69350-42070 LOCK ASSY, BACK DOOR <i>Auto</i>	1.00	505.50	✓	505.50 ✓
43	7	T69430-48030 STRIKER ASSY, BACK <i>ner</i>	1.00	44.40	X	44.40 X
44	8	T76801-52520 GARNISH SUB-ASSY, <i>cra</i>	1.00	486.20	✓	486.20 ✓
45	9	T75403-75010 EMBLEM SUB-ASSY, <i>ner</i>	1.00	67.40	✓	67.40 ✓
46	0	T75442-52550 PLATE, BACK DOOR <i>ner</i>	1.00	44.20	✓	44.20 ✓
47	1	T75442-52560 PLATE, LUGGAGE COMPT <i>ner</i>	1.00	44.20	✓	44.20 ✓
		<i>Door assy back RH woped/cra \$607.20</i>				

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153
	Document No. 0	
	Document Date 04/07/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
48	2	T75441-52270 PLATE, LUGGAGE COMPT	1.00	49.30		49.30
49	3	U90269-06017 RIVET	2.00	4.10		8.20
50	4	T81561-52E50 LENS & BODY, RR	1.00	398.40		398.40
51	5	T81551-52E50 LENS & BODY, RR	1.00	398.40		398.40
52	6	T81590-52400 LAMP ASSY, RR, LH	1.00	356.40		356.40
53	7	T81581-52410 LENS & BODY, RR	1.00	312.40		312.40
54	8	T81920-47010 REFLECTOR ASSY,	1.00	65.00		65.00
55	9	T81910-47010 REFLECTOR ASSY,	1.00	65.00		65.00
56	0	T89341-K0060 CN SENSOR, ULTRASONIC,	1 2.00	393.60		787.20
57	1	T89341-K0060 AI SENSOR, ULTRASONIC,	1 2.00	393.60		787.20
58	2	T89348-K0231 RETAINER, ULTRASONIC	4.00	43.10		172.40
59	3	T89348-58130 CLIP, ULTRASONIC	2.00	12.90		25.80
60	4	T89997-30100 ANTENNA, ELECTRICAL	1.00	78.00		78.00
61	5	T85130-52280 MOTOR ASSY, RR WIPER	1.00	921.50		921.50
62	6	T85241-52250 ARM, RR WIPER	1.00	87.50		87.50
63	7	T85242-72010 BLADE, RR WIPER	1.00	46.20		46.20
64	8	T75606-52090 MOULDING SUB-ASSY, outer	1.00	169.20		169.20
65	9	T75088-52010 MOULDING SUB-ASSY,	1.00	79.40		79.40
66	0	TZMCSG-ZXST2 CARNECTED ZXS-T2 2CH DVR	1.00	211.27		211.27
67	1	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

**Borneo Motors**

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA**

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153
	Document No. 0	
	Document Date 04/07/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
68	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>nee</i>	1.00	200.00		200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

31,948.97

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	30,831.63
	Please acknowledge receipt of vehicle	Parts 16,435.27	GST 7.00%	2,158.21
		Labour 13,132.00	Less	0.00
		Sublet 1,264.36		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	32,989.84

Customer Copy



Borneo Motors

Inchicape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153
	Document No. 39012838	
	Document Date 05/08/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	42001	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	04/07/2022 11.35	05/08/2022 11.04

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
48	3	T68810-52210 HINGE ASSY, BACK	2.00	112.40		224.80
49	4	T90189-06242 GROMMET, SCREW	8.00	1.90		15.20
50	5	T89341-K0060 A1 SENSOR, ULTRASONIC,	1.00	393.60		393.60
51	6	TBLVUE-DR750 XPLU BLACKVUE DR750X PLUS 2CH	1.00	530.84		530.84

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			21,939.10
	Please acknowledge receipt of vehicle	Parts 11,042.74	GST 7.00% 1,535.74
		Labour 10,172.00	
		Sublet 724.36	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 23,474.84

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****TAX INVOICE**

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153
	Document No. 39012838	
	Document Date 05/08/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	42001	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	04/07/2022 11.35	05/08/2022 11.04

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-GBH8999A ACC DATE:03/07/2022 DRIVE IN:04/07/2022 DATE-IN:04/07/2022 DATE SURVEY:05/07/2022 NO OF REPAIR DAYS:12 DAYS BY:MARCUS(LKK)				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	0619			366.36
3	S	BP-SUBLET REAR NUMBER PLATE	0263			68.00
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR	*			180.00
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST	*			180.00
6	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR	*			360.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE,REAR END PANEL				120.00
8	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS	*			462.00
9	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM	0741			290.00
10	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA	*			180.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****TAX INVOICE**

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153
	Document No. 39012838	
	Document Date 05/08/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	42001	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	04/07/2022 11.35	05/08/2022 11.04

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI	*			360.00
		LGATE				
12	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS	*			4320.00
		STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				
13	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR	*			2950.00
		EAS				
14	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
15	Z	BP-SUNDRY AUTO TAILGATE LOCK ASSY(SET)				850.00
16	1	T52159-5C906 COVER, RR BUMPER	1.00	311.90		311.90
17	2	T52563-52060 RETAINER, RR BUMPER,	1.00	65.00		65.00
18	3	T52576-52210 RETAINER, RR BUMPER	1.00	108.70		108.70
19	4	T52562-52100 RETAINER, RR BUMPER,	1.00	65.00		65.00
20	5	T52575-52230 RETAINER, RR BUMPER	1.00	108.70		108.70
21	6	T52453-52902 GUARD, RR BUMPER,	1.00	541.10		541.10
22	7	L75392-35220 RETAINER, OUTSIDE	4.00	4.30		17.20
23	8	T58307-52750 PANEL SUB-ASSY, BODY	1.00	755.10		755.10
24	9	T58387-52060 C0 PLATE, RR FLOOR	1.00	343.90		343.90
25	0	T58410-52160 B0 BOARD ASSY, DECK	1.00	574.10		574.10
26	1	T64740-52870 C0 PANEL ASSY, DECK	1.00	642.80		642.80
27	2	T67005-52E01 PANEL SUB-ASSY, BACK	1.00	1543.90		1543.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138
	Document No. 39012838	
	Document Date 05/08/2022	Mobile: 98750153

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	42001	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	04/07/2022 11.35	05/08/2022 11.04

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	3	T67881-52240 WEATHERSTRIP, BACK	1.00	354.00		354.00
29	4	T68105-52770 GLASS SUB-ASSY, BACK	1.00	1285.80		1285.80
30	5	T64813-K2020 DAM, BACK WINDOW	1.00	22.00		22.00
31	6	T76801-52520 GARNISH SUB-ASSY,	1.00	486.20		486.20
32	7	T75403-75010 EMBLEM SUB-ASSY,	1.00	67.40		67.40
33	8	T75442-52550 PLATE, BACK DOOR	1.00	44.20		44.20
34	9	T75442-52560 PLATE, LUGGAGE COMPT	1.00	44.20		44.20
35	0	T75441-52270 PLATE, LUGGAGE COMPT	1.00	49.30		49.30
36	1	T90269-06017 RIVET	2.00	4.10		8.20
37	2	T81561-52E50 LENS & BODY, RR	1.00	398.40		398.40
38	3	T81590-52400 LAMP ASSY, RR, LH	1.00	356.40		356.40
39	4	T89341-K0060 C0 SENSOR, ULTRASONIC,	1.00	393.60		393.60
40	5	T89348-K0231 RETAINER, ULTRASONIC	4.00	43.10		172.40
41	6	L89348-58130 CLIP, ULTRASONIC	2.00	12.90		25.80
42	7	T75606-52090 MOULDING SUB-ASSY,	1.00	169.20		169.20
43	8	T75088-52010 MOULDING SUB-ASSY,	1.00	79.40		79.40
44	9	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
45	0	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
46	1	U90467-05164 C0 CLIP	4.00	2.40		9.60
47	2	T64771-52300 B0 COVER, SPARE WHEEL	1.00	418.80		418.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.	Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153		
			Document No. 39012838			
			Document Date 05/08/2022			

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	42001	21893	67/TP/SLD0048A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB340L002770	M15AY085298	60	Sam San Joi	04/07/2022 11.35	05/08/2022 11.04

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
48	3	T68810-52210 HINGE ASSY, BACK	2.00	112.40		224.80
49	4	T90189-06242 GROMMET, SCREW	8.00	1.90		15.20
50	5	T89341-K0060 A1 SENSOR, ULTRASONIC,	1.00	393.60		393.60
51	6	TBLVUE-DR750 XPLU BLACKVUE DR750X PLUS 2CH	1.00	530.84		530.84

For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary		Total	21,939.10
		Please acknowledge receipt of vehicle	Parts	11,042.74	GST 7.00%	1,535.74
			Labour	10,172.00		
			Sublet	724.36	Less	0.00
			Lubrication/Fluid	0.00		
			Others	0.00	Amount Due	23,474.84

Customer Copy