



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153		
			Document No. 0				
			Document Date 04/07/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBBAB340L002770		M15AY085298	60	Sam San Joi	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-GBH8999A ACC DATE:03/07/2022 DRIVE IN:04/07/2022 DATE-IN:04/07/2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				366.36	
3	S	BP-SUBLET REAR NUMBER PLATE				68.00	
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00	
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00	
6	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				360.00	
7	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE,REAR END PANEL AND REAR LH FENDER				180.00	
8	S	BP-SUBLET REMOVE & INSTALL FUEL TANK TO ASSIST REP AIR				360.00	
9	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				462.00	
10	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				290.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153		
			Document No. 0				
			Document Date 04/07/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBBAB340L002770		M15AY085298	60	Sam San Joi	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				180.00	
12	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				360.00	
13	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
14	B	BP-LAB2 REPAIR & REALIGN REAR CHASSIS PANEL				720.00	
15	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				5760.00	
16	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				4720.00	
17	1	T52159-5C906 COVER, RR BUMPER	1.00	311.90		311.90	
18	2	T52563-52060 RETAINER, RR BUMPER,	1.00	65.00		65.00	
19	3	T52576-52210 RETAINER, RR BUMPER	1.00	108.70		108.70	
20	4	T52562-52100 RETAINER, RR BUMPER,	1.00	65.00		65.00	
21	5	T52575-52230 RETAINER, RR BUMPER	1.00	108.70		108.70	
22	6	T52453-52902 GUARD, RR BUMPER,	1.00	541.10		541.10	
23	7	L75392-35220 RETAINER, OUTSIDE	4.00	4.30		17.20	
24	8	T58307-52750 PANEL SUB-ASSY, BODY	1.00	755.10		755.10	
25	9	T58311-52310 PAN, RR FLOOR	1.00	879.90		879.90	
26	0	T58316-52230 EXTENSION, RR FLOOR	1.00	74.40		74.40	
27	1	T61602-52880 PANEL SUB-ASSY,	1.00	1061.60		1061.60	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153			
			Document No. 0					
			Document Date 04/07/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKBBAB340L002770		M15AY085298	60	Sam San Joi	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
28	2	T61056-52010 PANEL SUB-ASSY, RR			1.00	95.50		95.50
29	3	T58387-52060 C0 PLATE, RR FLOOR			1.00	343.90		343.90
30	4	T58410-52160 B0 BOARD ASSY, DECK			1.00	574.10		574.10
31	5	T64771-52300 B0 COVER, SPARE WHEEL			1.00	418.80		418.80
32	6	T64777-10020 CUSHION, SPARE WHEEL			1.00	109.30		109.30
33	7	T64740-52870 C0 PANEL ASSY, DECK			1.00	642.80		642.80
34	8	T90467-05164 C7 CLIP			4.00	1.90		7.60
35	9	S62940-02200 DUCT ASSY, QUARTER V			1.00	80.60		80.60
36	0	T67005-52E01 PANEL SUB-ASSY, BACK			1.00	1543.90		1543.90
37	1	T67881-52240 WEATHERSTRIP, BACK			1.00	354.00		354.00
38	2	T67751-52220 C0 BOARD, BACK DOOR			1.00	318.30		318.30
39	3	T76827-52070 RETAINER, BACK DOOR			1.00	23.40		23.40
40	4	T68105-52770 GLASS SUB-ASSY, BACK			1.00	1285.80		1285.80
41	5	T64813-K2020 DAM, BACK WINDOW			1.00	22.00		22.00
42	6	T69350-42070 LOCK ASSY, BACK DOOR			1.00	505.50		505.50
43	7	T69430-48030 STRIKER ASSY, BACK			1.00	44.40		44.40
44	8	T76801-52520 GARNISH SUB-ASSY,			1.00	486.20		486.20
45	9	T75403-75010 EMBLEM SUB-ASSY,			1.00	67.40		67.40
46	0	T75442-52550 PLATE, BACK DOOR			1.00	44.20		44.20
47	1	T75442-52560 PLATE, LUGGAGE COMPT			1.00	44.20		44.20
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153				
		Document No. 0					
		Document Date 04/07/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBAB340L002770		M15AY085298	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
48	2	T75441-52270 PLATE, LUGGAGE COMPT		1.00	49.30		49.30
49	3	U90269-06017 RIVET		2.00	4.10		8.20
50	4	T81561-52E50 LENS & BODY, RR		1.00	398.40		398.40
51	5	T81551-52E50 LENS & BODY, RR		1.00	398.40		398.40
52	6	T81590-52400 LAMP ASSY, RR, LH		1.00	356.40		356.40
53	7	T81581-52410 LENS & BODY, RR		1.00	312.40		312.40
54	8	T81920-47010 REFLECTOR ASSY,		1.00	65.00		65.00
55	9	T81910-47010 REFLECTOR ASSY,		1.00	65.00		65.00
56	0	T89341-K0060 C0 SENSOR, ULTRASONIC,		2.00	393.60		787.20
57	1	T89341-K0060 J2 SENSOR, ULTRASONIC,		2.00	393.60		787.20
58	2	T89348-K0231 RETAINER, ULTRASONIC		4.00	43.10		172.40
59	3	T89348-58130 CLIP, ULTRASONIC		2.00	12.90		25.80
60	4	T89997-30100 ANTENNA, ELECTRICAL		1.00	78.00		78.00
61	5	T85130-52280 MOTOR ASSY, RR WIPER		1.00	921.50		921.50
62	6	T85241-52250 ARM, RR WIPER		1.00	87.50		87.50
63	7	T85242-72010 BLADE, RR WIPER		1.00	46.20		46.20
64	8	T75606-52090 MOULDING SUB-ASSY,		1.00	169.20		169.20
65	9	T75088-52010 MOULDING SUB-ASSY,		1.00	79.40		79.40
66	0	TZMCSG-ZXST2 CARNECTED ZXS-T2 2CH DVR		1.00	211.27		211.27
67	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA		2.00	108.00		216.00
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
						Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No. S1000003 / ICCI1		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			Document No. 0		Mdm Chia Wey Ching Mabel 138 Bishan Street 12 #08-444 Singapore 570138 Mobile: 98750153			
			Document Date 04/07/2022					
			Year	Model	Variant	Reg. Date	Reg. No.	Kilometers
2020	MXPJ10R	BHXNBQ A1	15/12/2020	SLD0048A	0	21893	67/TP/SLD0048A	
Chassis No.			Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTDKBBAB340L002770			M15AY085298	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
68	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 30,831.63		
				Please acknowledge receipt of vehicle		GST 7.00% 2,158.21		
				Parts 16,435.27		Less 0.00		
				Labour 13,132.00				
				Sublet 1,264.36				
				Lubrication/Fluid 0.00				
		Others 0.00		Amount Due 32,989.84				

Customer Copy