

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22006385/UVY3M4**Date:** 08/07/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30002108176
Claimant Vehicle No :	FBR4238L	Insured Vehicle No :	YQ2080U
Date of Loss:	19/06/2022	Nature of Claim:	TP
		Claim No:	277367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR4238L	Engine No:	G3M1E050479
Make & Model:	YAMAHA AEROX 155A, 155cc	Chassis No:	MLESG584111050491
Reg. Date:	18/06/2020 (Man. Year: 2020)	Odometer:	44690 km
Colour:	Blue		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-80-14	Rear Tyre Size:	140-70-14
Front Left Side:	IRC 6 mm	Rear Left Side:	IRC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,911.20	1,628.40	5,282.80	76.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	280.00	630.00	69.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,821.20	1,908.40	5,912.80	75.60
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	7,821.20	1,500.00	6,321.20	80.82

INSPECTION

Date of Assignment:	05/07/2022	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit Singapore 417883
Date Inspected:	05/07/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Jul 2022)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR4238L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Not Necessary	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	52.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	48.00 FL	*- FL
7	1		*SET SIDE MIRROR	N/s Cut (1Piece Only)	120.00 FL	*48.00 FL
8	1		*HANDLE-BAR	Serviceable	135.00 FL	*- FL
9	1		*HANDLE-BAR BALANCER (O/S)	Cut	80.00 FL	*45.00 FL
10	1		*SET HAND GRIP	Not Necessary	95.00 FL	*- FL
11	1		*BRAKE LEVERS (N/S)	Cut	180.00 FL	*68.00 FL
12	1		*FOOTSTEP PANEL (N/S)	Cut	510.00 FL	*185.00 FL
13	1		*FOOTSTEP LOWER PANEL (N/S)	Cut	680.00 FL	*160.00 FL
14	1		*EXHAUST ASSY	Not Necessary	680.00 FL	*- FL
15	1		*EXHAUST PROTECTOR (SCRATCHED)	Not Consistent With The Impact	48.00 FL	*- FL
16	1		*DROVE BELT COVER	Cut	285.00 FL	*175.00 FL
17	1		*AIR FILTER COVER	Cut	125.00 FL	*80.00 FL
18	1		*SIDE STAND	Repair	85.00 FL	*- FL
19	1		*MAIN STAND	Cut	135.00 FL	*135.00 FL
20	1		*SET FAIRING COVER	Cut	1,450.00 FL	*680.00 FL
21	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
22	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
23	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
24	1		*REAR BOX	Cut	480.00 FS	*200.00 FS
25	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
26	1		*AEROX EMBLEM	Not Necessary	60.00 FS	*- FS
27	1		*SET NUMBER PLATE	Front Necessary	38.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,572.00	1,786.00
- List Item Discount on L Items 10.00/10.00% (\$)	660.80	157.60
Total Parts (\$)	6,911.20	1,628.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD) (NPA)	New	0.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	450.00	280.00
Gross Labour Cost (\$\$)			910.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >