

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 01 Aug 2022

Preliminary Advice

Insured Vehicle No	: YQ2080U	Accident Date	: 19/06/2022
TP Vehicle No	: FBR4238L	Assignment Date	: 05/07/2022
Make	: YAMAHA AEROX 155A	Est. Duration of Repair	: 3
Date of Inspection	: 05/07/2022		
Inspection At	: EROFIA MOTOR TRADING PTE LTD - (KAKI BUKIT) (HQ) 1 KAKI BUKIT AVENUE 6, #02-62 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	7,821.20
Revised Amount	:S\$	1,500.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,500.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	11,000.00
COE / PARF Rebate	:S\$	3,176.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,824.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.