

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|--|----------------|-------|---------------------|--|
| | ALLIANZ INSURAN | NCE SINGAPORE PTE LTD | | Ref: | CS/AIS22006391/Vvy3 | |
| | 79 ROBINSON RO #09-01 SINGAPOR | | | Date: | 05/07/2022 | |
| | | | | Code: | AIS | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLD 980H | Veh. Inspected | l | YQ 6768T | |
| | Policy No. | SP2002177834 | Coverage (\$) | | 0.00 | |
| | Claim No. | 202222005486KC | Excess (\$) | | 0.00 | |
| | Assign From | CHAN KIAN CHUAN | Assign Date | | 05/07/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | Steering | | | | |
| | Brakes | Modification | | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. | 5. General Information | | | | | |
| | Accident Date | 29/06/2022 | Inspection Dat | е | 05/07/2022 | |
| | Survey held at | TEAMWORK GARAGE PTE LTD |) | | | |
| | | 53 UBI AVENUE 1 #01-24 SINGAPORE 408934. | | | | |
| 5a. Remarks | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |