

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3298A
 CHUA TOON HWA
 BLK 54 GEYLANG BAHRU
 08-3595
 SINGAPORE 330054
 TEL : FAX :
 PH : 96945657
 ATTN :

*not Adherent
 her
 12/7/22
 L/S # 1950
 4 days*

ESTIMATE BILL

Number : EB00006022
 Date : 05/07/2022
 Case No : AD00012832
 Vehicle No : SLE5751P
 Chassis : RU11202013
 Year of Mfr : 2016
 Policy No : 5082474383
 Model : HONDA VEZEL

Term: CASH

| Sn | DESCRIPTION | QTY | U PRICE | DISC | AMOUNT |
|--|---|-----|--------------------|------|-----------------|
| 1 | FRONT FENDER LH <i>Dis</i> | 1.0 | 538.10 | 20 | 430.48 |
| 2 | FRONT FENDER WHEEL ARCH GARNISH LH <i>Dis</i> | 1.0 | 163.90 | 20 | 131.12 |
| 3 | HEADLAMP ASSEMBLY LH <i>See</i> | 1.0 | 1,997.60 | 20 | 1,598.08 |
| 4 | FRONT FENDER INNER SHIELD LH <i>See</i> | 1.0 | 112.90 | 20 | 90.32 |
| 5 | FRONT FENDER INNER SHIELD CLIP LH <i>See</i> | 6.0 | 23.40 3.90 | 20 | 18.72 |
| 6 | FRONT BUMPER RETAINER LH <i>See</i> | 1.0 | 15.00 | 20 | 12.00 |
| 7 | FRONT BUMPER <i>To In</i> | 1.0 | 507.10 | 20 | 405.68 |
| 8 | FRONT WHEEL HUB BEARING LH <i>11</i> | 1.0 | 158.10 | 20 | 126.48 |
| 9 | FRONT LOWER ARM LH <i>11</i> | 1.0 | 439.90 | 20 | 351.92 |
| 10 | FRONT KNUCKLE ARM LH <i>11</i> | 1.0 | 269.70 | 20 | 215.76 |
| 11 | FRONT SHOCK ABSORBER LH <i>11</i> | 1.0 | 56.00 | 20 | 44.80 |
| 12 | FRONT STABILIZER LINK LH <i>11</i> | 1.0 | 56.00 | 20 | 44.80 |
| 13 | FRONT WHEEL RIM LH <i>See</i> | 1.0 | 833.00 | 20 | 666.40 |
| List Price - Parts Sub Total | | | | | 4,136.56 |
| 14 | FRONT TYRE LH <i>See</i> | 1.0 | 280.00 | 0 | 280.00 |
| 15 | FRONT DOOR LH - REPAIR <i>See</i> | 1.0 | | | |
| Special Nett Price - Parts Sub Total | | | | | 280.00 |
| Parts Total | | | | | 4,416.56 |
| 16 | LABOUR TO REMOVE & REFIT NECESSARY PARTS | 1.0 | 700.00 | 0 | 700.00 |
| 17 | SPRAY PAINT ON THE AFFECTED AREAS | 1.0 | 800.00 | 0 | 800.00 |
| 18 | ANTI-RUST COATING | 1.0 | 100.00 | 0 | 100.00 |
| 19 | TWO WHEEL ALIGNMENT | 1.0 | 80.00 | 0 | 80.00 |
| 20 | WIRING | 1.0 | 40.00 | 0 | 40.00 |
| 21 | TO REMOVE & REFIT UNDERCARRIAGE | 1.0 | 350.00 | 0 | 350.00 |
| Labour 1 Sub Total | | | | | 2,070.00 |
| SINGAPORE DOLLARS : SIX THOUSAND NINE HUNDRED FORTY AND CENTS SIXTY-TWO ONLY | | | Less Excess | | 0.00 |
| | | | SUBTOTAL | | 6,486.56 |
| | | | GST 7.00% | | 454.06 |
| | | | TOTAL | | 6,940.62 |

Handwritten notes on the right side of the table, including 'Dis', 'See', 'To In', '11', 'See', '400', '600', '30', '20', '17', 'X'.

Date of accident : 04/07/2022 03:40 PM. Place : SLIP ROAD OF CTE TOWARDS JALAN TOA PAYOH

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature: _____

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE _____

AUTHORISED SIGNATURE _____

Handwritten calculations on the right side:
 P-2080.50
 20%
 1664.4
 1130

 2794.4
 302

 1956.

* N = Item not subjected to GST