

MYCAR CONSULTANT PTE LTD
 Reg no: 2016058787
 Address: 53 Ubi Crescent #01-23 Paya Ubi Industrial Park Singapore 408934
 HP: 98888885

MYCAR
 CONSULTANT

• To resurvey the repair of the following:
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimation

Date: 5/7/2022
 Vehicle: SNF5926Z
 Make / Model: TOYOTA ALTIS
 Chassis: CHINA TAIPING

No.	Description	Unit	Unit Price	Amount	
Parts Replacement:					
1	FRONT DOOR LH <i>✓ Acc</i>	1	\$ 1,215.00	\$ 1,215.00	1150 ✓
2	FRONT DOOR HINGES <i>X NN</i>	2	\$ 65.00	\$ 130.00	X
3	FRONT FENDER LH <i>X Repair</i>	1	\$ 567.00	\$ 567.00	X
4	FRONT FENDER EMBLEM <i>✓ Acc</i>	1	\$ 62.00	\$ 62.00	✓
				\$ 1,974.00	862.50
			Less 25%	\$ 493.50	-25%
			Total	\$ 1,480.50	646.87
S/Nett items:					
1	FRONT DOOR INNER TRIM CLIPS <i>✓ Acc</i>	1	\$ 50.00	\$ 50.00	20 ✓
				\$ 50.00	
Labour to:					
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	XNY
2	REMOVE AND REPAIR FRONT DOOR MECHANISM	1	\$ 200.00	\$ 200.00	60
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00	20
4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00	400
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00	250
				\$ 1,400.00	
					730
total - 1396.87			Parts Replacement Amount	\$ 1,530.50	
L/S - 1117.49			Total Amount for Labour	\$ 1,400.00	
= 1100			Total Amount	\$ 2,930.50	

3 Days.
 L/S
 After repair photos.
 Gino Ricoy
 5/7/22