

MYCAR CONSULTANT PTE LTD
 The Repairer of the following:
 Reg no: 2016058787
 Address: 53 Ubi Crescent #01-23 Paya Ubi Industrial Park Singapore 408934
 HP: 98888885

• To resurvey the repair work
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimation

Date: 5/7/2022
 Vehicle: SNF5926Z
 Make / Model: TOYOTA ALTIS
 Chassis: CHINA TAIPING

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT DOOR LH / <i>one</i>	1	\$ 1,215.00	\$ 1,215.00
2	FRONT DOOR HINGES X <i>NN</i>	2	\$ 65.00	\$ 130.00
3	FRONT FENDER LH X <i>Repair</i>	1	\$ 567.00	\$ 567.00
4	FRONT FENDER EMBLEM / <i>one</i>	1	\$ 62.00	\$ 62.00
				\$ 1,974.00
			Less 25%	\$ 493.50
			Total	\$ 1,480.50
S/Nett items:				
1	FRONT DOOR INNER TRIM CLIPS / <i>one</i>	1	\$ 50.00	\$ 50.00
				\$ 50.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND REPAIR FRONT DOOR MECHANISM	1	\$ 200.00	\$ 200.00
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
				\$ 1,400.00
			Parts Replacement Amount	\$ 1,530.50
			Total Amount for Labour	\$ 1,400.00
			Total Amount	\$ 2,930.50

3 Days.
 L/S
 After repair photos.
 Gino Ricoy
 5/7/22

20
 XUV
 60
 20
 400
 250