

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/555/2022/NK
DATE : 5-Jul-22
WIP : 31502

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 06/07/2022

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

OWNER'S NAME : MR HUN YEW CHUA
ADDRESS : 267 GREENWOOD AVENUE
#267
SINGAPORE 286871
TELEPHONE : HP +65 9168 4077
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : D- 21098055MVPC
VEHICLE NO : SLS 1640 D
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 11/9/2017
ENGINE NO : CHZ 511028
CHASSIS NO :
MILEAGE : -
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jul-22
PLACE OF ACCIDENT : BUKIT TIMAH, SUNSET AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 1640 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY.	S/N \$ 360.00 /	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 /	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER AND CHARGE AIR COOLER. TO REINSTALL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	1 X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	2100 - ✓
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER.	\$ 3,000.00	2200 - ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	\$ 192.00 /	✓
TOTAL LABOUR CHARGES		\$ 10,202.00	



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 1640 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / BR	1	\$ 2,432.00 /	2432
2	FRONT BUMPER FIXING PARTS ? X nn	1	\$ 195.00	
3	FRONT BUMPER GUIDE SECTION RH / BT	1	\$ 43.00 /	42.80
4	FRONT BUMPER CENTRE GRILLE ? X nn ?	1	\$ 179.00	
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE ?	1	\$ X nn 571.00	
6	FRONT BUMPER CLOSING ELEMENT RH / BR	1	\$ 318.00 /	318
7	FRONT BUMPER COVER TRIM RH ? X nn	1	\$ 182.00	
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER RH ?	1	\$ X nn 42.00	
9	RADIATOR GRILLE / cut	1	\$ 1,577.00 /	1577
10	RADIATOR CLOSING ELEMENT ? X nn	1	\$ 210.00	
11	FRONT BUMPER AIR GUIDE GRILLE RH / cut	1	\$ 210.00 /	210
12	FRONT REINFORCEMENT BEAM ? / BT	1	\$ 847.00 /	846.50
13	FRONT BUMPER FOAM FILLER PC ? / BR	1	\$ 211.00 /	211
14	FRONT COVER TOP COVER ? X nn	1	\$ 136.00	
15	STICKER FOR AIR CONDITIONER ? / nc	1	\$ 9.00 /	8.30
16	STICKER FOR "CAUTION" ? / nec	1	\$ 16.00 /	15.50
17	SIGNAL HORN LOW TONE RH ? X nn	1	\$ 213.00	
18	FRONT FENDER RH / on	1	\$ 954.00 /	954
19	POP RIVET / nc	5	\$ 19.00 /	19
20	FRONT FENDER ATTACHMENTS PARTS ? X nn	1	\$ 75.00	
SUB TOTAL SPARE PARTS			\$ 8,439.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 1640 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET- RH ✓ BT	1	\$ 46.00 / 45.50		
22	FRONT FENDER BRACE am ? / BT	1	\$ 107.00 / 107		
23	BONNET LID HINGE - LH / RH X nn	2	\$ 136.00		
24	FRONT WHEEL HOUSING LINER - RH ✓ CR4	1	\$ 183.00 / 183		
25	BONNET ✓ DV	1	\$ 3,348.00 / 3348		
26	BONNET LID HINGE - LH / RH X nn	2	\$ 136.00		
27	BONNET EDGE PRTOECTION — m	1	\$ 31.00 / 30.90		
28	BONNET CATCH HOOK X nn	1	\$ 100.00		
29	BONNET STRICKER- RH X nn	1	\$ 123.00		
30	BONNET LID LOCK W SWITCH X nn	1	\$ 228.00		
31	BONNET CATCH HOOK X nn	1	\$ 71.00		
32	BONNET BOWDEN CABLE CENTRE X m	1	\$ 64.00		
33	BONNET COVER X nn	1	\$ 11.00		
34	LED HEADLIGHT RH ✓ BR	1	\$ 5,878.00 / 5878		
35	LED HEADLIGHT POWER MODULE ? X nn	1	\$ 850.00		
36	LED HEADLIGHT CONTROL UNIT ? X nn	1	\$ 625.00		
37	LED HEADLIGHT HEAT SINK RH ? X nn	1	\$ 818.00		
38	LED HEADLIGHT HOSE RH ? X nn	1	\$ 46.00		
39	LED HEADLIGHT LIFT CYCLINDER — BR	1	\$ 156.00 / 155.50		
40	LED HEADLIGHT CYCLINDER HOSE ? / TN	1	\$ 78.00 / 77.80		
			: \$ 13,035.00		
SUB TOTAL SPARE PARTS					

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 1640 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	LED HEADLIGHT BRACKET <i>1 (sensor bracket)</i>	1	\$ <i>X nn</i>	21.00	
42	RADIATOR COOLANT <i>1 X nn</i>	1	\$	806.00	
43	COOLANT <i>1 X nn</i>	6	\$	282.00	
44	AIR GUIDE RH <i>1 X nn</i>	1	\$	28.00	
45	AIR GUIDE SEAL OUTER - RH <i>1 X nn</i>	1	\$	9.00	
46	AIR GUIDE UPPER - CENTRE <i>1 X nn</i>	1	\$	14.00	
47	NOISE INSULATION <i>1 X nn</i>	1	\$	376.00	
48	FRONT NO PLATE <i>1 ne</i>	S/N	\$	60.00	<i>60</i>
49	SUNDRIES <i>1 ne</i>	1	\$	400.00	<i>7.00</i>
TOTAL SPARE PARTS		:	\$	23,470.00	
TOTAL LABOUR CHARGES		:	\$	10,202.00	
GRAND TOTAL		:	\$	33,672.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
6/7/12, 11.00

00-L1 M
EX(11)-7
P/P
W R y
6 \$ 45

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT