

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR FENDER RH <i>repair</i>	2,030.30	-30.00	1,421.21
Total Parts (S\$)					1,421.21

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
Sub Total (S\$)					0.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,500.00	0.00	1,500.00 <i>200</i>
Gross Labour Cost (S\$)					1,500.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Supply Spray Terostat Sealant On The Cutting Areas.	30.00	0.00	30.00 <i>X11</i>
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	50.00	0.00	50.00 <i>X11</i>
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00 <i>200</i>
Gross Labour Cost (S\$)					880.00

< END OF ESTIMATES >

LKK Auto Consultants have to notify the Repairer of the following:

- To remedy the damage to a vehicle
- To display name and price during survey
- Parts price and labour cost
- Third party guarantee and "Prejudice" basis
- No item to be replaced
- Supply of parts and labour surveyed and is to be approved by the Insurance Company

Ackd _____

Sd _____

Date _____

*Rasul**Hp 90010068**3 days**P/P**13/07/22 @**1010**Resy after repair*