

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

SINGAPORE ACCIDENT ESTIMATE

IMPORTANT NOTICE

EST. No: EST0029719
P S Defence

Page 1 of 1
Your ref: TP-XD 1987R Lonpac
Job No: 72818
Our ref: 22.07.07
Payment
Date: 5/7/2022

Attn: SKD 1279E
Vehicle No: SKD 1279E
Vehicle Model: Nissan Teana
Accident on: 4/7/2022
Country/State of Loss

Not Authorised
11 Pp & 240d
Runny After Paint
4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett Item:					
1.00	Pc	Front fender RH	922.40	10.00	830.16
1.00	Pc	Front fender inner shield RH	173.40	10.00	156.06
8.00	Pcs	Front fender inner shield clips RH	5.00	10.00	36.00
1.00	Pc	Front bumper	950.40	10.00	855.36
1.00	Pc	Front bumper outer retainer RH	73.90	10.00	66.51
1.00	Pc	Front bumper inner retainer RH	40.50	10.00	36.45
Labour & Misc:					
1.00		Towing fee	70.00		70.00
1.00		Computerised wheel alignment	60.00		60.00
1.00		To dismantle + refix side skirt RH in order to renew parts	450.00		450.00
1.00		To spray paint (include blending front door RH)	600.00		600.00

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date: repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."