



**Thiam Heng Huat Pte Ltd**176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721  
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: AUDI A5

Engine/Chassis No.: WAUZZZF54JA022113


Date of accident:

Damaged area: O/S Rear

Date: 06/07/2022

Claim Type: TP

VRN: SKE7781B

*NOT Authorized  
L1 Smg & 3300t  
Resurvey After Paint*

| List items    |                                                               |     |             |             |   |
|---------------|---------------------------------------------------------------|-----|-------------|-------------|---|
| S/N           | Parts description                                             | QTY | UNIT PRICE  | AMOUNT      |   |
| 1             | Rear bumper <i>1918 Bul/cm</i>                                | 1   | \$ 2,390.00 | \$ 2,390.00 | ✓ |
| 2             | Rear bumper reinforcement <i>R</i>                            | 1   | \$ 974.60   | \$ 974.60   | X |
| 3             | Rear bumper side retainer <i>Ln</i>                           | 2   | \$ 96.20    | \$ 192.40   | X |
| 4             | Rear bumper tow cover <i>Ln</i>                               | 1   | \$ 62.15    | \$ 62.15    | X |
| 5             | Rear bumper diffuser <i>724. mg/cm</i>                        | 1   | \$ 798.40   | \$ 798.40   | ✓ |
| 6             | End panel <i>R</i>                                            | 1   | \$ 971.25   | \$ 971.25   | X |
| 7             | End panel top garnish <i>Ln</i>                               | 1   | \$ 385.30   | \$ 385.30   | X |
| 8             | Rear bumper center bracket <i>CM</i>                          | 1   | \$ 90.00    | \$ 90.00    | ✓ |
| 9             | Rear bumper reflector o/s <i>85 CM</i>                        | 1   | \$ 298.50   | \$ 298.50   | ✓ |
| 10            | Rear bumper lower cowlng <i>Ln</i>                            | 1   | \$ 221.25   | \$ 221.25   | X |
| 11            | Rear bumper sensor holder <i>Ln</i>                           | 2   | \$ 26.40    | \$ 52.80    | X |
| 12            | Motion sensor trunk release module harness <i>718.6 short</i> | 1   | \$ 894.60   | \$ 894.60   | ✓ |
| 13            | Motion sensor trunk release module <i>Ln</i>                  | 1   | \$ 1,467.20 | \$ 1,467.20 | X |
| Subtotal      |                                                               |     |             | \$ 8,798.45 |   |
| List discount |                                                               |     |             | 5.00%       |   |
| Total         |                                                               |     |             | \$ 8,358.53 |   |

| Special nett items |                                              |     |            |             |   |
|--------------------|----------------------------------------------|-----|------------|-------------|---|
| No.                | Parts description                            | QTY | UNIT PRICE | AMOUNT      |   |
| 1                  | Rear bumper reverse sensor <i>0135 short</i> | 1   | \$ 294.75  | \$ 589.50   | ✓ |
| 2                  | Exhaust tip "AKRAPOVIC" o/s <i>Ln</i>        | 2   | \$ 480.00  | \$ 960.00   | X |
| 3                  | Rear bumper clips <i>Ln</i>                  | 10  | \$ 5.50    | \$ 55.00    | ✓ |
| 4                  | End panel sealant <i>Ln</i>                  | 1   | \$ 120.00  | \$ 120.00   | X |
| 5                  | End panel top garnish clips <i>Ln</i>        | 8   | \$ 5.50    | \$ 44.00    | X |
| 6                  | Sundries <i>Ln</i>                           | 1   | \$ 50.00   | \$ 50.00    | X |
| Total              |                                              |     |            | \$ 1,818.50 |   |

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Repair Estimate

| Labour       |                                                                                                                                             |           |             |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------|
| No.          | Description                                                                                                                                 | Work unit | Amount      |
| 1            | To dismantle / renew the accident damaged portion.<br>To panel beat, reshape, straighten, orientate and align repair / replacement parts.   | 6         | \$ 1,200.00 |
| 2            | To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings. | 0.25      | \$ 50.00    |
| 3            | Supply spray paint material and necessary items to respray affected area / panel.                                                           | 5         | \$ 1,000.00 |
| 4            | To rust proof all affected portions after repair.                                                                                           | 0.5       | \$ 100.00   |
| Total labour |                                                                                                                                             |           | \$ 2,350.00 |

2501

156

4401

X

|                      |              |
|----------------------|--------------|
| Estimate Grand Total | \$ 12,527.03 |
|----------------------|--------------|

LKK Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: \_\_\_\_\_  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_