



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22006403/Uvy3e2	Date: 15/07/2022
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMF 3660P	Veh. Inspected	GBG 8808Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10015822 /CD	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	05/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE 2.0 DX (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	TRH2005046831	Colour	PINK	
Odometer	8827 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	DUNLOP	8 mm	
L/H Front Tyre	195/80 R15	DUNLOP	8 mm	
R/H Rear Tyre	195/80 R15	DUNLOP	8 mm	
L/H Rear Tyre	195/80 R15	DUNLOP	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	31/03/2022	Inspection Date	05/07/2022	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #01-87 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	