



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2302860
3 ANSON ROAD #16-00	INV Date	08/05/2023
SPRINGLEAF TOWER	Reference	CC6/CTI22006404/Tya3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SMC 7438E
Insured Veh.	GU 3656U
Claim No.	SNM22D204682/C02
Policy No.	DMCVSNW00013662201
Accident Date	04/07/2022
Inspection Date	20/07/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (8%)</b>	<b>32.00</b>
<b>Grand Total</b>	<b>432.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22006404/Tya3q2 Date: 08/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GU 3656U	Veh. Inspected	SMC 7438E
Policy No.	DMCVSNW00013662201	Coverage (\$)	0.00
Claim No.	SNM22D204682/C02	Excess (\$)	0.00
Assign From		Assign Date	20/07/2022
2. Vehicle Particulars & Condition			
Make & Model	KIA CARENS	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAHU815VJ7209020	Colour	BLUE
Odometer	173185 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/07/2022	Inspection Date	20/07/2022
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 7438E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	752.00	576.00
1	REAR BUMPER LOWER COVER	CUT	290.00	189.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	53.00	-
1	REAR BUMPER REFLECTOR RH	CUT	204.00	116.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR END PANEL	NOT NECESSARY	709.00	-
1	REAR END GARNISH	NOT NECESSARY	94.00	-
1	TAILAMP RH	CUT	622.00	428.00
	LESS 10% DISCOUNT		-	-133.90
			2,774.00	1,205.10
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			200.00	-
<b><u>LABOUR</u></b>				
	SPRAY PAINTING REAR BUMPE AND REAR BUMPER COVER .		400.00	250.00
	REPLACE REAR AREA INCLUDING FITTING ,CUT,WELD AND RE-ALIGN .		600.00	200.00
	REMOVE AND REFIT REAR REVERSE SENSOR .		80.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING .		30.00	30.00
			1,110.00	510.00
<b>GRAND TOTAL</b>			<b>4,084.00</b>	<b>1,715.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,350.00</b>

Report Ref No. CC6/CTI22006404/Tya3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 7438E

INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SMC 7438E**

**RE-INSPECTION**

