





# Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C

## Estimate

48 Toh Guan Road East (Enterprise Hub)  
#02-146, Singapore 608586  
Tel: 64688834 Fax: 67228585  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-354-TG  
DATE : 5-Jul-2022  
POLICY NO. :  
VEHICLE REG. NO. : **SMC7438E**  
VEHICLE MAKE : KIA CARENS 2018

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<b>SPARE PARTS</b>				
1	Rear Bumper	1	\$ 752.00	\$ <i>del</i> 752.00
2	Rear Bumper Lower Cover	1	\$ 290.00	\$ <i>del</i> 290.00
3	Rear Bumper Retainer RH	1	\$ 53.00	\$ <i>X</i> 53.00
4	Rear Bumper Reflector RH	1	\$ 204.00	\$ <i>del</i> 204.00
5	Rear Bumper Clip	10	\$ 5.00	\$ <i>del</i> 50.00
6	Rear End Panel	1	\$ 709.00	\$ <i>X</i> 709.00
7	Rear End Garnish	1	\$ 94.00	\$ <i>X</i> 94.00
8	Tailamp RH	1	\$ 622.00	\$ <i>del</i> 622.00
<b>Total Special Nett</b>				<b>\$ 2,774.00</b>
<b>SPECIAL NETT</b>				
9	Reverse Sensor	1	\$ 200.00	\$ 200.00
<b>Total Special Nett</b>				<b>\$ 200.00</b>
<b>LABOUR</b>				
10	Spray painting Rear Bumper and Rear Bumper Cover	1	\$ 400.00	\$ <i>250</i> 400.00
11	Replace Rear Area including Fitting, Cut, Weld and Re-align	1	\$ 600.00	\$ <i>200</i> 600.00
12	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ <i>30</i> 80.00
13	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ <i>30</i> 30.00
<b>Total Labour</b>				<b>\$ 1,110.00</b>
<b>Amount Before Excess</b>				<b>\$ 4,084.00</b>
<b>Add GST @ 7%</b>				<b>285.88</b>
<b>Total Amount Payable</b>				<b>\$ 4,369.88</b>

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

<b>Total Labour</b>	<b>\$ 1,110.00</b>
<b>Amount Before Excess</b>	<b>\$ 4,084.00</b>
<b>Add GST @ 7%</b>	<b>285.88</b>
<b>Total Amount Payable</b>	<b>\$ 4,369.88</b>

*Tanfiki 97495749/62563521*

*WP' 20/7/22 @ 2pm  
1/5 Resurvey after repair  
tanfiki @ lhaauto.com  
2 days*

**LKK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to valuation from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: